

(08/11/13) wef

AS REC. BY: *MCW*

REF:

*CC6/A1620012485/UGS3***ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I.: (\$)

☐☐

Preli. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐☐☐☐

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

24/11/20
 B1 involved LFA#60340
 age 1-8-2022 haulage
 1/5#2200 confirmed with Alan.

hal centre

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

VEHICLE No: SKU 8300R

1PC	REAR BUMPER	2088.75	\$2,400.15	X
1PC	REAR BUMPER DIFFUSER	R	\$655.20	X
1PC	REAR BUMPER REINFORCEMENT	R	\$751.32	X
1PC	REAR BUMPER REINFORCEMENT PLATE	one 162-30	\$215.00	X
1SET	REAR BUMPER CLIPS	new	\$50.00	X
1PC	REAR END PANEL	R	\$885.00	X
			\$4,956.67	

TO CHECK WIRING
TO DISMANTLE & REFIX REAR PDC SENSOR
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
TO RESET & REPROGRAMME FAULT CODE
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

11	\$50.00	X
	\$80.00	50
11	\$100.00	X
11	\$100.00	X
	\$420.00	250
	\$500.00	400
TOTAL	\$6,206.67	

not Addressed
R
1/3 @ 2200
13/11/20
2 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 2301.05
100
P- 2070.94
R- 700.00
2770.94
202
2216.75