



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0840/2020/NS
DATE	:	4-Nov-20
WIP	:	56201

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS AW YUIN SIN
ADDRESS	:	72 BAYSHORE ROAD #20-14 SINGAPORE 469988
TELEPHONE	:	HP +65 93823590
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2100508778-03
VEHICLE NO	:	SLN 2668 U
MODEL CODE	:	AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR	:	28/4/2017
ENGINE NO	:	CVN 034617
CHASSIS NO	:	WAUZZZF49HA135587
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	31-Oct-20
PLACE OF ACCIDENT	:	MCE TOWARDS ECP



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 2668 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00	✓
1			
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000 ✓
3			
4	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	\$ 2,900.00	1100 ✓
	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT TEST.	S/N \$ 520.00	280 ✓
5			
SUB TOTAL LABOUR CHARGES		: \$ 6,150.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 2668 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	TO REMOVE AND TRANSFER REAR PARKING AID AND		
6	REAR LID KICK SENSOR, CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	✓
7	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00	X
8	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$ 400.00	X
9	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	X
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	X
SUB TOTAL LABOUR CHARGES		: \$ 2,960.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 2668 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
11	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG ETC.	S/N \$ 1,400.00	X
12	TO DISMANTLE REAR BUMPER. CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00 750	
13	TO RESPRAY REAR BUMPER, LHS REAR FENDER, DOOR ENTRANCES, LHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 4,550.00 1100	
14	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY.	S/N \$ 350.00	X
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 20,502.00</u>	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 2668 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1	FRONT BUMPER	\$	2,111.00	X
2	FRONT BUMPER FIXING PARTS	\$	282.00	X
3	FRONT BUMPER SECURING STRIP	2	70.00	X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	208.00	X
5	FRONT BUMPER AIR GUIDE - LH	Not	62.00	X
6	FRONT BUMPER AIR GUIDE GRILLE - LH	New	134.00	X
7	FRONT BUMPER GUIDE SECTION - LH		36.00	X
8	FRONT FENDER - LH	Defect	758.00	✓
9	FRONT FENDER ATTACHMENT PARTS	New	200.00	X
10	FRONT FENDER CLOSING ELEMENT - LH	New	49.00	X
11	FRONT FENDER BRACKET - LH	?	35.00	?
12	FRONT FENDER BRACE - LH FRONT	?	117.00	?
13	WHEEL HOUSING LINER - LH	New	237.00	X
14	WHEEL HOUSING LINER ATTACHMENT PARTS	New	90.00	X
15	WHEEL SPOILER	New	73.00	X
16	STONE CHIP GUARD	New	50.00	✓
17	FENDER TOP LEDGE COVER - UPPER	?	31.00	?
18	FENDER TOP LEDGE COVER - LOWER	?	23.00	?
19	BONNET IMPACT PROTECTION - CENTRE	2 New	27.00	X
20	BONNET IMPACT PROTECTION - LH	1 New	28.00	X
SUB TOTAL SPARE PARTS			\$	4,621.00



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO, SLN 2668 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21	BONNET IMPACT PROTECTION - RH <i>new</i>	\$	27.00	X
22	FRONT ALUMINIUM RIM - LH <i>ok</i>	\$	589.00	✓
23	REAR BUMPER <i>Reps</i>	\$	2,181.00	X
24	REAR BUMPER FIXING PARTS <i>2 new</i>	\$	72.00	X
25	REAR BUMPER SECURING STRIP <i>1 new</i>	\$	220.00	X
26	REAR BUMPER GUIDE SECTION - LH <i>Reps</i>	\$	44.00	X
27	REAR FENDER - LH	\$	2,644.00	X
28	REAR WINDSCREEN <i>2 new</i>	\$	1,141.00	X
29	SIDE WINDOW - LH	\$	609.00	X
30	PRIMER	\$	19.00	X
31	WHEEL HOUSING LINER - LH <i>3 new</i>	\$	237.00	X
32	EXTERIOR MIRROR MOUNTING - LH	\$	1,077.00	X
33	MIRROR CAP - LH <i>ok</i>	\$	261.00	✓
34	MIRROR GLASS - LH <i>2 new</i>	\$	1,196.00	X
35	LED HEADLIGHT - LH	\$	7,693.00	X
36	1/4 GLASS SEALANT	S/N	100.00	X
37	REAR WINDSCREEN SEALANT <i>2</i>	S/N	200.00	X
38	METAL FILLER POWDER	S/N	280.00	X
39	STONE CHIP	S/N	180.00	X
40	CAVITY WAX	S/N	140.00	X
41	ACRYLIC SEALANT <i>new</i>	S/N	180.00	X
42	SUNDRIES <i>?</i>	\$	400.00	?
TOTAL SPARE PARTS				:
			\$	24,111.00
TOTAL LABOUR CHARGES				:
			\$	20,502.00
GRAND TOTAL				:
			\$	44,613.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian
13/11/20

Not Authorised, 08 Days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT