



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

TP ALG.
Jasper.

Adrain (LKK)

Attn: The Motor Claims Department
Your Insured veh no : SMQ 5414 M
AIG ASIA PACIFIC INSURANCE PTE LTD.
78 Shenton Way
07-16 Chartis Building
Singapore 079120

WITHOUT PREJUDICE

(By Email Only)

16.11.2020

11:00 AM

Date: 13/11/2020

Dear Sir / Madam

Estimate Cost of repair for vehicle GBF 4980 P & SMQ 5414 M on 07/11/2020@10:10:00

To Supply:-

1pc	Front Bumper	Rebond	619.70	\$	589.70	✓
10pcs	Frnt Bumper Clips	new		\$	50.00	30
1pc	Front Head Lamp Lower Garnish LH	Repair	557.73	\$	329.30	x
1pc	Wheel Hup Cap	int		\$	136.80	80 (sn)
1pc	Wheel Hup Cap	Repaired	S.N. 80	\$	136.80	x
				\$	1,242.60	
				\$	124.26	
				\$	1,118.34	
				\$	350.00	200
				\$	450.00	300
				\$	1,918.34	

To dismanlte & replace damage parts, panel beat where necessary.

To putty, apply primer & spray paint on the affecte portion.

500.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrain Lj
2/8 16/11/20
03 Days

total: 113773
(P/P)