

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012503/QGA3Q2
Date: 10/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900085656
Claimant Vehicle No :	SLM6252P	Insured Vehicle No :	SML1457S
Date of Loss:	12/11/2020	Nature of Claim:	TP
		Claim No:	7362918267SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM6252P		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5919225
Reg. Date:	03/04/2017 (Man. Year: 2016)	Chassis No:	RU31219214
Colour:	Silver	Odometer:	223570 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,712.24	1,756.80	1,955.44	52.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,600.00	1,600.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,912.24	3,356.80	3,555.44	51.44
Approved Total (Overridden) (S\$)		2,700.00		

(S\$)	6,912.24	2,700.00	4,212.24	60.94
+ GST 7.00/7.00% (S\$)	483.86	189.00	294.86	60.94
Nett Amount (S\$)	7,396.10	2,889.00	4,507.10	60.94
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,091.00		

INSPECTION

Date of Assignment: 13/11/2020

Date Inspected: 13/11/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Lion City Rentals Pte Ltd (HQ)
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/R SIDE BUMPER	Repair	300.00 FL	*- FL
2	1		*R/R FENDER WHEEL MOULDING	Crumpled	300.00 FL	*198.00 FL
3	1		*R/R FENDER	Crumpled	1,560.00 FL	*953.00 FL
4	1		*R/R DOOR ASSY	Crumpled	1,600.30 FL	*1,020.00 FL
5	1		*RH TAILLAMP	Serviceable	780.00 FL	*- FL
6	1		*SET FENDER CLIPS	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,620.30	2,191.00
- List Item Discount on L Items 20.00/20.00% (\$)	908.06	434.20
Total Parts (\$)	3,712.24	1,756.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING R/R FENDER WHEEL ARCH MOULDING AND R/R SIDE BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS .ALSO INCLUDE CUTTING OUT R/R DOOR ASSY ,R/R FENDER TO FACILITAT REPLACEMENT OF DAMAGED PARTS	New	1,200.00	800.00
2	TO RESPRAY R/R SIDE BUMPER ,R/R FENDER R/R DOOR AND R/R WHEEL ARCH MOULDING ,RH LOWER SKIRT	New	1,400.00	700.00
3	TO COFIGURE CAR KEYLESS NETWORK BACK TO FACTORY SPECIFICATION	New	200.00	50.00
4	TO REMOVE AND INSTALL REAR UPHOLSTERY AND SEATS OUT TO FACILITATE REPAIRS	New	400.00	50.00
Gross Labour Cost (\$\$)			3,200.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >