

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20012506/KSF3E2

**Date:** 21/12/2020

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001179844		
<b>Claimant Vehicle No :</b>	SGD6525J	<b>Insured Vehicle No :</b>	SLZ5314H		
Date of Loss:	09/11/2020	Nature of Claim:	TP	Claim No:	249548

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGD6525J</b>	Engine No:	CCZ168815
Make & Model:	SKODA SUPERB, 2.0 Elegance (A)	Chassis No:	TMBBH93T1C9010466
Reg. Date:	11/05/2012 (Man. Year: 2012)	Odometer:	124577 km
Colour:	Metallic Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,427.86	3,437.37	990.49	22.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	1,170.00	220.00	15.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,817.86</b>	<b>4,607.37</b>	<b>1,210.49</b>	<b>20.81</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,650.00</b>		
<b>(\$\$)</b>	5,817.86	3,650.00	2,167.86	37.26
<b>+ GST 7.00/7.00% (\$\$)</b>	407.25	255.50	151.75	37.26
<b>Nett Amount (\$\$)</b>	<b>6,225.11</b>	<b>3,905.50</b>	<b>2,319.61</b>	<b>37.26</b>

### INSPECTION

Date of Assignment:	13/11/2020		
Date Inspected:	17/11/2020	Inspected At:	BLK 176 SIN MING DRIVE #03-09
Estimated Period of Repair:	4.0 days		Repairer : Bifrost Auto Pte Ltd (sin Ming) (HQ)

**Adjuster:** KENNETH KONG

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2020)
Parts:	143	SKODA SUPERB 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGD6525J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER (LH)	Bent	632.55 FN	*632.55 FN
2	1		*FRONT FENDER UNDER SHIELD (LH)	Serviceable	185.25 FN	*- FN
3	1		*FRONT DOOR (LH)	Warped	2,356.65 FN	*2,150.50 FN
4	1		*FRONT DOOR CHROME MOUNTING (LH)	Serviceable	289.15 FN	*- FN
5	1		*FRONT DOOR RUBBER (LH)	Necessary	156.25 FN	*156.25 FN
6	1		*FRONT RIM (LH)	Dented	1,300.00 FN	*880.00 FN
F=Franchise part. N=NettItemDisc.						
Sub Total (S\$)					4,919.85	3,819.30
- Nett Item Discount on N Items 10.00/10.00% (S\$)					491.99	381.93
Total Parts (S\$)					4,427.86	3,437.37

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	500.00	400.00
2	SPRAY PAINTING CHARGE	New	700.00	600.00
3	ANTI-RUST	New	80.00	60.00
4	TRANSFER OF DOOR FITTING	New	50.00	50.00
5	WHEEL ALIGNMENT	New	60.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,390.00</b>	<b>1,170.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >