

Date : 12-Nov-20

Registration no. : SMF8605S / Volkswagen Scirocco 1.4L AT TSI 1372Q5

DOA : 11-Nov-20

Estimate No. : 19A011_SMF8605S_SCIROCCO

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Tailgate ✓ DD	2088.90	1607 ✓
2	1	Tailgate logo ✓ NEC	80.00	✓
3	1	Tailgate weatherstrip ✓ TN	225.00	✓
4	1	Tailgate inner lock ✓ Jammed	192.00	✓
5	1	Tailgate windscreen moulding ✓ NEC	188.00	✓
6	1	Tailgate trimboard ✓ CRU	344.80	✓
7	1	Rear bumper ✓ DD	1436.90	1122.30 ✓
8	1	Rear bumper side retainer @ SGD 120.60 ✓ BR	241.20	✓
9	1	Rear bumper centre retainer ✓ BR	164.30	✓
10	1	Rear bumper reflector @ SGD 89.00 ✗ NN	178.00	
11	2	Rear bumper reinforcement ✗ NN	552.30	
12	1	Rear number plate lamp ✓ CUT	133.00	✓
13	1	Rear end panel ✓ DD	811.00	✓
14	1	Rear end panel top garnish ✓ CRU	225.50	✓
15	1	Taillamp @ SGD 511.00 ✓ BR	1022.00	✓
16	1	Taillamp lower bracket @ SGD 126.00 ✗ NN	252.00	
17	1	Exhaust pipe ✗ NN	1420.00	
18	1	Exhaust pipe mounting @ SGD 87.50 ✗ NN	175.00	
			9729.90	
Less 10%			972.99	
			8756.91	

Date : 12-Nov-20

Registration no. : SMF8605S / Volkswagen Scirocco 1.4L AT TSI 1372Q5

DOA : 11-Nov-20 Estimate No. : 19A011_SMF8605S_SCIROCCO

S/N	Qty	Item	Amount
-----	-----	------	--------

SPECIAL NETT ITEMS

1	1	Sundries ✓ NEC	60.00 30
2	1	Tailgate windscreen primer & cleaner ✓ NEC	60.00 20
3	1	Tailgate windscreen inner seal ✓ NEC	60.00 20
4	1	Tailgate windscreen sealant ✓ NEC	80.00 40
5	1set	Tailgate trimboard clips ✓ NEC	35.00 20
6	1	Rear CCTV camera 'iRoad' ✓ Shorted	420.00 350
7	1set	Rear bumper clips ✓ NEC	60.00 30 ✓
8	1	Rear bumper defuser × NN	800.00 ×
9	1set	Rear end panel top garnish clips ✓ NEC	30.00 ✓
10	1	Rear end panel sealant ✓ NEC	80.00 30 ✓
11	2set	Rear fender inner shield clips @ SGD 30.00 × NN	60.00 ×
			1745.00
Parts Total			10501.91

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on rear accident area.	1800.00 800 ✓
2	1	Check wiring system after disconnect and connect.	80.00 30 ✓
3	1	R&R interior upholstery.	200.00 ×
4	1	R&R tailgate component.	100.00 50 ✓
5	1	R&R tailgate windscreen.	180.00 120 ✓
6	1	R&R exhaust pipe assy.	200.00 ×
7	1	R&R reverse sensor and test.	80.00 30 ✓
8	1	To apply undercoating for rust roofing.	200.00 30 ✓
9	1	Spray painting on rear accident area.	1500.00 600 ✓
Labour Total			4340.00

Total Parts and Labour Cost of Repair

14841.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)

12/11/20

Without Prejudice

L/S

Resurvey After Spray

5 repair days