

ASS. REC. BY:

REF:

B19

## ASSIGNMENT

From:

Date:

2/12/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKN 4921 L

at Workshop m/s

Maur Image

of

19 Lowing Taa Payoh

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Aur 10.300.rr

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

\$188k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Veh No:

SKN4921L

Yr Regn:

20 Jan 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Forester

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

66532

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/55 R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Cat 2 35750

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Rep. Formed:

Lump Sum / L.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL



19 Lorong 8 Toa Payoh  
Singapore 319255



LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval by LKK Auto Consultants

### ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

Acknowledged by Repairer  
Signature:

|                           |                                |
|---------------------------|--------------------------------|
| REG NO: SKN4921L          | MODEL : FORESTER 2.0XT AWD CVT |
| REF: INS/IC/CHI/0216/2020 | YEAR: 20-JUN-2014              |
| ENGINE NO: FA20H925888    | CHASSIS NO: JF1SJGK85EG026246  |
| DOA: 11 / 11 / 2020       | TOA: 2115 HRS                  |
| TYPE OF CLAIM: TP         | INS COMPANY: AIG               |

| S/N          | NATURE OF JOB                                                 | AMOUNT     |
|--------------|---------------------------------------------------------------|------------|
| 1.           | REPAIR/REPLACE REAR BUMPER, REAR TAILGATE AND PANEL           | \$ 1000.00 |
| 2.           | RESPRAY REAR BUMPER, REAR TAILGATE AND PANEL                  | \$ 800.00  |
| 3.           | TRANSFER TAILGATE MECHANISM                                   | \$ 95.00   |
| 4.           | REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIRS | \$ 114.00  |
| 5.           | REMOVE & INSTALL REAR WINDSCREEN                              | \$ 240.00  |
| 6.           | TO CONDUCT REAR LIGHTING TEST                                 | \$ 28.00   |
| 7.           | TO CONDUCT REAR ANTI-RUST COATING                             | \$ 290.00  |
| 8.           | TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES X MN              | \$ 300.00  |
| 9.           | TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM               | \$ 145.00  |
| 10.          | SUNDRIES                                                      | \$ 100.00  |
| Total Labour |                                                               | \$ 3112.00 |

500  
400  
—  
—  
—  
—  
X NN  
—  
20  
1542

|                   |                      |
|-------------------|----------------------|
| DATE APPROVAL:    |                      |
| TIME APPROVAL:    |                      |
| SURVEY BY:        | Quo Qiang - 82880282 |
| HP / EMAIL:       | before paint photos. |
| BEFORE PAINT: MIE |                      |
| DAYS GIVEN:       |                      |

5-6 Days.  
02/12/2020

Estimate

Date 11 / 12 / 2020

001 / 002

|         |                        |                |                   |
|---------|------------------------|----------------|-------------------|
| Name    | QUOTATION FOR SKN4921L | Tel (Home)     |                   |
| Address |                        | Tel (Office)   |                   |
| E-Mail  |                        | Tel (Portable) |                   |
|         |                        | Fax            |                   |
|         |                        | Model Name     | S13               |
|         |                        | Body Model     | SJGBKK8           |
|         |                        | Vin-Code       | JF1SJGK85EG026246 |

| Part Number  | Part Code Name                                          | Part Code                    | Q'ty | Price    |   |
|--------------|---------------------------------------------------------|------------------------------|------|----------|---|
| 63019SG000   | GLASS-REAR GATE / <i>MC</i>                             | FIG-621 63011                | 1    | 799.20   | ✓ |
| 63232SG010   | RUBBER-REAR GATE / <i>MC</i>                            | FIG-621 63232                | 1    | 12.60    | ✓ |
| 63232SG000   | DAM RUBBER-REAR GATE GLASS / <i>MC</i>                  | FIG-621 63232C               | 2    | 7.20     | ✓ |
| 60809SG0509P | PANEL-REAR GATE / <i>Buc</i>                            | FIG-620 60810                | 1    | 1,072.80 | ✓ |
| 63516SG001   | WEATHER STRIP-REAR GATE <i>X</i> NN                     | FIG-901 63516                | 1    | 111.60   |   |
| 94026SG000VH | TRIM PANEL-REAR SKIRT <i>X</i> NN                       | FIG-940 94046                | 1    | 36.00    |   |
| 57704SG012   | BUMPER-FACE, REAR / <i>re</i>                           | FIG-591 57704A               | 1    | 540.00   | ✓ |
| 57711SG0219P | BACK BEAM COMPLETE-REAR <i>✓</i> BT                     | FIG-591 57711D               | 1    | 288.00   | ✓ |
| 57707SG080   | BRACKET-REAR BUMPER SIDE, RIGHT <i>X</i>                | FIG-591 57707H               | 1    | 14.40    |   |
| 57707SG090   | BRACKET-REAR BUMPER SIDE, LEFT <i>X</i>                 | FIG-591 57707I               | 1    | 14.40    |   |
| 57707SG060   | BRACKET-REAR BUMPER CORNER, RIG <i>X</i><br>HT          | FIG-591 57707AC<br><i>NN</i> | 1    | 18.00    |   |
| 57707SG070   | BRACKET-REAR BUMPER CORNER, LEF <i>X</i><br>T           | FIG-591 57707AD              | 1    | 18.00    |   |
| 57731SG010NN | COVER-REAR BUMPER <i>X</i>                              | FIG-591 57731C               | 1    | 12.60    |   |
| 84912SG021   | LENS & BODY-REAR COMBINATION L <i>X</i> NN<br>AMP RIGHT | FIG-842 84912B               | 1    | 388.80   |   |
| 91111SG000   | GARNISH ASSEMBLY-REAR GATE, B / <i>BR</i>               | FIG-914 91111P               | 1    | 144.00   | ✓ |
| 91713SG000   | PROTECTOR-REAR GARNISH / <i>MC</i>                      | FIG-914 91713                | 1    | 21.60    | ✓ |
|              |                                                         | Page-Total                   |      | 3,499.20 |   |

|      |
|------|
| Memo |
|      |

|             |
|-------------|
| Grand Total |
| 3,718.80    |

|  |
|--|
|  |
|--|

|     |
|-----|
| Tel |
|-----|

Estimate

Date 11 / 12 / 2020

002 / 002

|         |                        |                |                   |
|---------|------------------------|----------------|-------------------|
| Name    | QUOTATION FOR SKN4921L | Tel (Home)     |                   |
| Address |                        | Tel (Office)   |                   |
| E-Mail  |                        | Tel (Portable) |                   |
|         |                        | Fax            |                   |
|         |                        | Model Name     | S13               |
|         |                        | Body Model     | SJGBKK8           |
|         |                        | Vin-Code       | JF1SJGK85EG026246 |

| Part Number | Part Code Name                    | Part Code      | Q'ty | Price        |
|-------------|-----------------------------------|----------------|------|--------------|
| 91713SG010  | PROTECTOR-REAR GARNISH            | FIG-914 91713C | 2    | 10.80        |
| 93033SG001  | ORNAMENT                          | FIG-914 93033D | 1    | 79.20        |
| 93079SG010  | LETTER MARK-REAR                  | FIG-919 93073Y | 1    | 64.80        |
| 93079SG030  | LETTER MARK-REAR                  | FIG-919 93073Y | 1    | 64.80        |
| WM002       | REAR NO PLATE<br>\$45 (NETT) X NN | Page-Total     |      | 219.60       |
|             |                                   | Sub-Total      |      | 3,718.80     |
|             |                                   | Total          |      | 3,718.80     |
|             |                                   | Tax            |      | 0.00         |
|             |                                   | Grand Total    |      | 3,718.80     |
|             |                                   |                |      | 3105         |
|             |                                   |                |      | -30%: 2173.5 |
|             |                                   |                |      | 3715.5       |

|      |
|------|
| Memo |
|      |

|             |
|-------------|
| Grand Total |
| 3,718.80    |

|  |
|--|
|  |
|--|

|     |
|-----|
| Tel |
|-----|