

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64796601
64796624 (Motorrad)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Damaged part(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Date: _____

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

13 NOV 2020

Estimate No. : b1 56549
Date Estimated : 13/11/2020
Prepared By : Foong Shiuh Jye

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Yip How Chee (Ye QiaoZhi)
82 Bedok North Rd
#06-316

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 460082

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP9237L	WBAJG120005N18497	23/10/2019	X1 sDrive18i	0

DESCRIPTION

To remove and install bumper rear cover, rear left door and attachments

To spray paint bumper rear cover, rear left door and door rear left handle

To check electrical wiring system at the front section for proper function including adjustment of headlights.

Sundries

VALUE

1700 2,550.00

1806 2,007.00

150 177.00

NEC ? 80.00

Total Labour 1: 4,814.00

DESCRIPTION

LH DOOR OUTER HANDLE PRIMED repair x
LH COVERING PRIMEND Xsu
REAR LH WHEEL ARCH TRIM sca-

QTY PRIC VALUE

1 95.55 95.55

1 47.80 47.80

1 151.80 151.80

Total Parts : 295.15

Claims OD (3rd Party) Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 23/11/2020 @ 1445 Excess S\$ _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 96006868 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail rasul@lkkauto.com

No. of Working Days Recommend 3 (4) days

Labour 1 : 4,814.00

Parts : 295.15

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 357.64

Grand Total : 5,466.79

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 56549**
Date Estimated : **13/11/2020**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -

Yip How Chee (Ye QiaoZhi)
82 Bedok North Rd
#06-316

Singapore 460082

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP9237L	WBAJG120005N18497	23/10/2019	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# EXPANDING RIVET BLACK nec 	1.40	20.00		28.00
---	------	-------	--	-------

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	28.00
Total Labour & Parts :	28.00