



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101884

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 23/03/2021
Reference CC3/CTI20012528/Era3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 2888L
Insured Veh. SMA 1584R
Claim No. SNM20D204346/LKKDS
Policy No. DMPCSNW00024322000
Accident Date 10/11/2020
Inspection Date 11/11/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20012528/Era3q2	
			Date: 23/03/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMA 1584R	Veh. Inspected	SHB 2888L	
Policy No.	DMPCSNW00024322000	Coverage (\$)	0.00	
Claim No.	SNM20D204346/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	11/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	KMHC851CVLU184577	Colour	YELLOW	
Odometer	4005 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	5 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	5 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	5 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/11/2020	Inspection Date	11/11/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2888L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER -FR BUMPER	TO REPAIR SEE LABOUR	430.90	-
10	HYUNDAI BUMPER COVER CLIP	NOT NECESSARY	22.00	-
1	MOULDING -FRONT BUMPER CTR	CUT	188.00	188.00
1	LAMP ASSY -HEAD RH	CUT	1,993.65	1,993.65
1	EMBLEM -BLUR DRIVE	NECESSARY	26.60	26.60
1	CAP ASSY -WHEEL HU	CUT	346.40	346.40
	LESS 20% DISCOUNT		-601.51	-510.93
			2,406.04	2,043.72
	<u>SPECIAL NETT ITEMS</u>			
1	(I40)FRONT DOOR LOGO CCPL M (SN)	NECESSARY	75.00	75.00
			75.00	75.00
	<u>LABOUR</u>			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF COVER -FR BUMPER .		700.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		650.00	600.00
	CHECK ALL LIGHTING .		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
	ADJUST FRONT WHEEL ALIGNMENT .		80.00	60.00
			1,530.00	1,040.00
	GRAND TOTAL		4,011.04	3,158.72
	RECOMMENDED COST OF REPAIRS			3,158.72

Report Ref No. CC3/CT120012528/Era3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 2888L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 2888L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

