

Our Job Ref No 305432948Date : 01.12.20ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr STEVEVehicle Reg No. SHB2888L CCPL10.11.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SMA1584R
2. The finalized amount shall be:
- | | |
|---|--------------------------|
| (a) Spare Parts after List discount | <u>\$2,118.72</u> |
| (b) Labour Charges | <u>\$1,040.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$3,158.72</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | <u>20%</u> |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs:
- 3
- working days.

- 4.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : LIM KWOK ENGTel : 62148316Fax : 65468156Signature : Name : SteveDate : 01/12/20**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Like

CHINA

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.11.2020

REPAIR ESTIMATE

Time: 17:59:38

Page: 1

Yellu

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305432948
REGN NO : SHB2888L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2020
DATE/TIME IN : 10.11.2020 13:40
ACCIDENT DATE : 10.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G	IONIQV4 COVER-FR BUMPER#	1 L	430.90	20.00	344.72	X	R
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	X	
0003 04-01-0104-2687-G	MOULDING-FRONT BUMPER CTR	1 L	188.00	20.00	150.40	/	CUT
0004 04-01-0104-2935-G	IONIQV4 LAMP ASSY-HEAD RH	1 L	1,993.65	20.00	1,594.92	/	CUT
0005 04-01-0104-3813-G	IONIQVC EMBLEM-BLUE DRIVE	1 L	26.60	20.00	21.28	/	MC
0006 28-01-0103-0007-A	(I40)FRT DOOR LOGO CCPL M	1 N	75.00	2.00-	75.00	/	MC
0007 03-01-0104-2137-G	IONIQV4 CAP ASSY-WHEEL HU	1 L	346.40	20.00	277.12	/	CUT

SUB-TOTAL : 2,481.04

JOB NATURE

0000 L	PANEL BEATING	700.00	320
0001 23-502	SPRAYPAINT ON AFFECTED AREA	650.00	600
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30

Steve (LKK) WL PM
11/11/20, 10.00am
3 hrs dys
P/P
My Bel 21

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 10.11.2020
Time: 17:59:38
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305432948
REGN NO : SHB2888L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2020
DATE/TIME IN : 10.11.2020 13:4
ACCIDENT DATE : 10.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 20-08 ADJUST FRONT WHEEL ALIGNMENT

80.00 60

SUB-TOTAL : 1,530.00

TOTAL : 4,011.04

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.12.2020

Time: 09:11:37

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305432948
REGN NO : SHB2888L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2020
DATE/TIME IN : 10.11.2020 13:40
ACCIDENT DATE : 10.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2687-G	MOULDING-FRONT BUMPER CTR	1 L	188.00	20.00	150.40
0002	04-01-0104-2835-G	IONIQV4 LAMP ASSY-HEAD LH	1 L	1,993.65	20.00	1,594.92
0003	04-01-0104-3813-G	IONIQVC EMBLEM-BLUE DRIVE	1 L	26.60	20.00	21.28
0004	28-01-0103-0007-A	(I40)FRT DOOR LOGO CCPL M	1 N	75.00	2.00-	75.00
0005	03-01-0104-2137-G	IONIQV4 CAP ASSY-WHEEL HU	1 L	346.40	20.00	277.12

SUB-TOTAL : 2,118.72

JOB NATURE

0000 L	PANEL BEATING	320.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	600.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	30.00
0004 20-08	ADJUST FRONT WHEEL ALIGNMENT	60.00

SUB-TOTAL : 1,040.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305432948
REGN NO : SHB2888L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2020
DATE/TIME IN : 10.11.2020 13:4
ACCIDENT DATE : 10.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,158.72

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :