



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

11-11-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAIG.

Celia.

Accident date: 11-11-2020

Estimated repair cost for vehicle no: SJM4142K MITSUBISHI LANCER 1.5 A '09

CHASSIS: JMYSRCY2A9U002691

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>new</i>		\$693.00	X.
2	2	Rear Boot Lid Side Reflector	\$236.00	\$472.00	X
3	2	Rear Tail Lamp	\$358.00	\$716.00	X
4	4	Rear Tail Lamp Clip	\$8.00	\$32.00	X
5	1 set	Rear Bumper Body Kit (Special Nett) <i>Behind</i>		\$3,500.00	200(SN)
6	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00	30
7	2	Rear Bumper Side Retainer <i>new</i>	\$41.00	\$82.00	✓
8	2	Rear Bumper Side Reflector <i>new</i>	\$38.00	\$76.00	X
9	1	Rear Bumper Beam <i>Bent</i>		\$168.00	✓
10	1	Rear Bumper Reinforcement <i>Bent</i>		\$284.00	✓
11	1	Rear Bumper Number Plate <i>new</i>		\$50.00	X
12	2	Rear Bumper Number Plate Lamp	\$39.00	\$78.00	X
13	1	Rear Bumper Reverse Sensor (Special Nett) <i>Behind</i>		\$350.00	200(SN)
14	1	Rear End Panel <i>Repair</i>		\$506.00	X
15	1	Rear End Panel Top Garnish		\$189.00	X
16	2	Rear Fender Inner Trim Board	\$212.00	\$424.00	X
17	16	Rear Fender Inner Trim Board Clip	\$6.50	\$104.00	X
18	1	Rear Spare Tyre Panel		\$621.00	X
19	1	Rear Spare Tyre Panel Top Cover		\$187.00	X
20	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00	X
21	2	Rear Exhaust (Special Nett) <i>Repair</i>	\$1,800.00	\$3,600.00	X
22	2	Rear Exhaust Mounting	\$80.00	\$160.00	X
23	1	Rear Centre Exhaust		\$1,387.00	X

Subtotal :- **\$14,181.00**

564

SX 1400

507.60

Labour charges

To remove & refit body kit	\$350.00 X
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & center exhaust	\$380.00 80
To check wiring	\$100.00 30
Tuff kote	960 \$150.00 X
Panel beating	\$800.00 400
Spray painting	\$800.00 400

Subtotal :- \$2,680.00

Total:- \$16,861.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2867.60

4/s: 23K.

03 Days.

2.3k

03 Days.