

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012537/BVF3E2
Date: 16/12/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMOCSNW00045492003
Claimant Vehicle No :	SMU8569J	Insured Vehicle No :	SGW505G
Date of Loss:	09/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204358/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU8569J	Engine No:	2ZR2G08117
Make & Model:	TOYOTA NOAH HYBRID, 1.8 (A)	Chassis No:	ZWR800423676
Reg. Date:	31/08/2020 (Man. Year: 2019)	Odometer:	27500 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,150.20	1,994.57	3,155.63	61.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,260.00	1,390.00	52.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,800.20	3,254.57	4,545.63	58.28
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	7,800.20	2,600.00	5,200.20	66.67

INSPECTION

Date of Assignment:	15/12/2020		
Date Inspected:	16/11/2020	Inspected At:	Team Auto Pro Pte Ltd - Sin Ming (HQ) 160 Sin Ming Drive #01-14 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	4.0 days		

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Dec 2020)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU8569J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE BUZZER	No such part	191.00 FL	*- FL
2	1		*TAILGATE ANTENNA SENSOR	Not Damaged	180.00 FL	*- FL
3	1		*REAR BUMPER	Cut	1,138.60 FL	*1,025.00 FL
4	2		*REAR BUMPER SIDE RETAINER	Necessary	374.40 FL	*270.20 FL
5	1		*REAR BUMPER LOWER BRACKET	Bent	65.20 FL	*65.20 FL
6	1		*REAR BUMPER REFLECTOR (2PCS)	Broken (1Pc Only)	363.20 FL	*105.00 FL
7	1		*REAR END PANEL	Dented	781.60 FL	*655.10 FL
8	1		*REAR END PANEL TOP GARNISH	Not Damaged	269.60 FL	*- FL
9	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
10	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
11	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
12	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
13	2		*REVERSE SENSOR	Short Circuit	500.00 FS	*200.00 FS
14	1		*REAR BUMPER BRACKET RH	Bent	160.00 FL	*125.60 FL
15	1		*REAR FENDER RH	Repair	1,200.00 FL	*- FL
16	1		*REAR FENDER SIDE GLASS MOULDING RH	Not Necessary	650.00 FL	*- FL
17	1		*REAR FENDER SEALANT	Necessary	100.00 FS	*40.00 FS
18	1		*REAR FENDER SIDE GLASS SEALANT	Not Necessary	100.00 FS	*- FS
19	1		*REAR FENDER SIDE GLASS INNER SEAL	Not Necessary	80.00 FS	*- FS
20	1		*REAR FENDER SIDE GLASS PRIMER & CLEANER	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,493.60	2,556.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,343.40	561.53
Total Parts (\$\$)	5,150.20	1,994.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REVERSE SENSOR	New	100.00	60.00
2	CHECK WIRING	New	100.00	30.00
3	UPHOLSTERY	New	200.00	0.00
4	DIAGNOTIC RESET FAULT CODE	New	300.00	120.00
5	PANEL BEAT	New	800.00	400.00
6	RUST PROOFING	New	100.00	50.00
7	SPRAY PAINTING	New	800.00	600.00
8	R&R REAR FENDER SIDE GLASS	New	250.00	0.00
Gross Labour Cost (\$\$)			2,650.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >