

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Park 2
Singapore 569541

Vehicle No : SLV 1748 L
Make : Toyota C-HR
Year : 2017

Fax 64816131

*Not Notified
11 Sep @ 2300hr
Runny After Paint
3 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear bumper	✓	
1 pc	Rear bumper reinforcement	?	
1 pc	Rear n/s bumper reflector garnish	7. photo	
1 pc	Rear buzzer	photo	
1 pc	Rear bumper center garnish	X	
1 pc	Rear lower bumper	✓	455.20
1 pc	Rear n/s bumper side retainer		
1 pc	Rear end panel	repair	
1 pc	Rear end panel inner garnish	X	

Bu	604	\$985.10	✓
R		\$483.20	—
DIT		\$125.60	—
ad		\$175.20	—
su		\$75.10	X
CM		\$655.70	✓
su		\$75.10	X
R		\$725.70	X
R		\$265.10	X
		\$3,565.80	
Less 25 %		\$891.45	
		\$2,674.35	

S Net

15 pcs	Rear bumper clip	✓
1 pc	Rear reverse sensor	✓

\$2.00	nc	\$30.00	✓
	short	\$200.00	✓

Labour Charges

Remove/renew the above parts including knocking, welding & cutting

To putty & spray paint on accident affected portion

Check and reconnect wiring

To anti-rust proofing

\$800.00 400L

\$800.00 440L

\$40.00 10L

nn \$100.00 X

Total \$4,644.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: