



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

SHARIOT PTE LTD

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

06-10-2020

Independent -
Stirley.

Accident date:

SLF9173G.

Estimated repair cost for vehicle no: ~~SLB8134S~~ TOYOTA SIENTA 1.5 G A '16

CHASSIS: NSP1707038010

S/n	Qty	Items	U/price	Amount	
1	1	Front Bonnet <i>Paper</i>		\$1,150.00	X
2	2	Front Bonnet Hinge <i>3 MP</i>	\$105.00	\$210.00	X
3	1	Front Bonnet Lock <i>1 per</i>		\$140.00	X
4	1	Front Brace Panel <i>new</i>		\$200.00	X
5	2	Front Head Lamp <i>Cracked</i>	\$1,930.00	\$3,860.00	✓
6	1	Front Bumper <i>Missing</i>		\$680.00	✓
7	2	Front Bumper Side Retainer <i>new</i>	\$72.00	\$144.00	X
8	10	Front Bumper Clips <i>new</i>	\$6.50	\$65.00	30
9	2	Front Bumper Fog Lamp	\$366.00	\$732.00	✓
10	2	Front Bumper Fog Lamp Cover <i>Missing</i>	\$112.00	\$224.00	✓
11	1	Front Bumper Emblem Logo		\$96.00	✓
12	1	Front Bumper Grille <i>2</i>		\$1,080.00	520.
13	8	Front Bumper Grille Clip <i>Missing</i>	\$6.50	\$52.00	✓
14	1	Front Bumper Towing Cover		\$65.00	✓
15	1	Front Bumper Center Garnish		\$276.00	✓
16	1	Front Bumper Number Plate		\$50.00	✓
17	1	Front Bumper Reinforcement <i>3 MP</i>		\$410.00	X
18	2	Front Bumper Reinforcement Bracket <i>new</i>	\$200.00	\$400.00	X
19	1	Front Bumper Top Beam <i>new</i>		\$400.00	X
20	1	Front Bumper Top Rubber <i>new</i>		\$156.00	X
21	1	Front Bumper Inner Foam <i>new</i>		\$120.00	X
22	1	Front R/H Fender Cowling <i>torn</i>		\$220.00	✓
23	8	Front R/H Fender Cowling Clips <i>new</i>	\$6.50	\$52.00	30
24	1	Front Wiper Tank <i>Deland</i>		\$139.50	X

6974.50

Subtotal :- \$10,921.50

\$230.87

Labour charges

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 30

Towing fee

~~\$150.00~~ 60

Panel Beating

1220 600 ~~\$800.00~~ 600

Spray Painting

500. ~~\$800.00~~ 600

Subtotal :- \$2,000.00

Total:- \$12,921.50

total: 6450.87
(P/P)

04 Days.

(P/P) Paint
take out.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: