



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

-	Ref : CS/TP20012547/Asd3e2
AUTOBAHN RENT A CAR PTE LTD 6001 BEACH ROAD, GOLDENMILE TOWER #08-06 SINGAPORE 199589- -	Date : 25-11-2020
Code : TP2	



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLE 9173G
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	06/11/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1707038010	Colour	YELLOW
Odometer	92243	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	FIRESTONE	6 mm
L/H Front Tyre	185/60 R15	FIRESTONE	6 mm
R/H Rear Tyre	185/60 R15	FIRESTONE	6 mm
L/H Rear Tyre	185/60 R15	FIRESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	Inspection Date	06/11/2020
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------