

# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorised  
L1 Sup &  
Purvey After Paint  
4-5 days

To: **AIG Asia Pacific Insurance Pte Ltd**

LKK Auto Consultants hence notify the Repairer of the following: Policy No: \_\_\_\_\_  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Third Party

12.11.2020

Accident Date : 11.11.2020

承接汽车烧焊喷漆及  
代理各种车辆赔偿

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

ESTIMATE

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mitsubishi Lancer EX" Reg. No. SJF9177P Claiming Against Your Insured Reg. No. SGV2248R			
1pc	Rear Bumper	3.80	895.00 N ✓
10pcs	Rear Bumper Clips		38.00 N ✓
1pc	Rear Bumper Reinforcement	17.50	232.00 N ✓
2pcs	Rear Bumper Brackets		35.00 N ✓
1pc	Rear Bumper Reflector LH		24.00 N ✓
1pc	Rear Bumper Top Beam	12.50	73.00 N ✓
4pcs	Rear Bumper Corner Retainer Rivets		50.00 N ✓
1pc	Rear Bumper Inner Boot Sensor		145.00 N ✓
1pc	Rear Number Plate Lamp		135.00 N ✓
1pc	Boot Badge 2.0 MIVES		55.00 N ✓
1pc	Boot Badge GT		46.00 N ✓
1pc	End Panel		556.00 N ✓
1pc	End Panel Garnish		163.50 N X
			2,447.50
			244.75
	Less 10%		2,202.75
	Rear Bumper Reverse Sensor		280.00 SN ✓
	Rear Number Plate (Chrome Letter)		120.00 SN ✓
	Boot Badge C&C		55.00 SN ✓
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Module, , Rewiring etc		120.00 200 ✓
	To Supply End Panel Body Sealant		60.00 7
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		50.00 7
	To Dismantle / Refit Rear Trunk Audio Power Amp, Woofer, Custom Made Board etc		250.00 7
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Spare Tyre Panel etc. Cnt, Weld End Panel and Parts Replacement		500-600 ✓ 900.00
	To Respray Affected Areas		600 ✓ 900.00
Total :			4,937.75