



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20012569/Avf3q2 Date: 08/02/2021	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLP 3513R	Veh. Inspected	SLJ 5689K	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10007975/JM	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	16/11/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HARRIER PREMIUM	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600081887	Colour	BLUE	
Odometer	81543 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	15/11/2020	Inspection Date	16/11/2020	
Survey held at	1 KAKI BUKIT AVE 6#01-52 (AUTOBAY)			
Repairer	SIN YU SIN WORKSHOP			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		