



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD

1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV No. AC2102992

INV Date 29/04/2021

Reference CC6/QBE20012570/Ura3q2

Code QBE

PROFESSIONAL SERVICE FEE

Vehicle No. SKT 7479X

Insured Veh. GBE 5677P

Claim No. VC014098

Policy No. 8-V0014389-MVA-R003

Accident Date 07/11/2020

Inspection Date 16/11/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC6/QBE20012570/Ura3q2	
			Date: 29/04/2021	
			Code: QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 5677P	Veh. Inspected	SKT 7479X
	Policy No.	8-V0014389-MVA-R003	Coverage (\$)	0.00
	Claim No.	VC014098	Excess (\$)	0.00
	Assign From		Assign Date	16/11/2020
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN QASHQAI (A)	c.c	1197
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	SJNFEAJ11U1401850	Colour	WHITE
	Odometer	101951 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/11/2020	Inspection Date	16/11/2020
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 7479X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	899.20	-
1	REAR FENDER OUTER PROTECTOR O/S	GRAZED	588.50	540.50
1	REAR BUMPER	TO REPAIR SEE LABOUR	796.70	-
1	SET REAR BUMPER CLIPS	NOT NECESSARY	30.00	-
1	REAR SPORT RIM O/S	TO REPAIR SEE LABOUR	1,200.00	-
	LESS 10% DISCOUNT		-	-54.05
			3,514.40	486.45
	<u>LABOUR</u>			
	TO CHECK WIRING .	NOT NECESSARY	50.00	-
	TO DISMANTLE & REFIX REAR REVERSE SENSOR .	NOT NECESSARY	80.00	-
	TO CONDUCT WHEEL ALIGNMENT.		80.00	60.00
	LABOUR FOR PANEL BEATING REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER O/S ,REAR BUMPER AND REAR SPORT RIM O/S .		450.00	200.00
	TO PUTTY & SPRAY PAINTING .		600.00	300.00
			1,260.00	560.00
GRAND TOTAL			4,774.40	1,046.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				800.00

Report Ref No. CC6/QBE20012570/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKT 7479X

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKT 7479X

RE-INSPECTION

