



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN : JEFFREY NG			Ref: CS3/AIG20009162/Gqf3e2-1 Date: 14/12/2020 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJX 9133X	Veh. Inspected	SGZ 76L	
Policy No.	1800042163	Coverage (\$)	0.00	
Claim No.	5905216335SG	Excess (\$)	0.00	
Assign From	JEFFREY NG	Assign Date	13/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600078503	Colour	BLACK	
Odometer	63446 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/45 R20	FALKEN	6 mm	
L/H Front Tyre	255/45 R20	FALKEN	6 mm	
R/H Rear Tyre	255/45 R20	FALKEN	6 mm	
L/H Rear Tyre	255/45 R20	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/08/2020	Inspection Date	01/09/2020	
Survey held at	GOLD AUTOWORKS PTE LTD 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	