

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Ergo Insurance Pte Ltd
 5 Temasek Boulevard
 #04-01 Suntec Tower Five
 Singapore 038985
 Tel : 6829 - 9170
 Fax : 6829 - 9247

Denise

Quotation
 DATE : 17.11.2020
 VEH NO : SLL7030L
 MODEL : Honda Vezel
 D O A : 14.11.2020
 YR REF : GBC6312X

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLL7030L (HONDA VEZEL)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp - LH & RH <i>xtol new</i>	2	77.00 X
2	Rear Bumper <i>Debond</i>	1	880.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	47.00 ✓
4	Rear Bumper Side Reflector - LH & RH <i>xtol new</i>	2	282.20 X
5	Rear Bumper Under Cover <i>Debond</i>	1	285.00 ✓
6	Rear End Panel <i>Dented</i>	1	585.00 ✓
7	Rear End Panel Top Garnish <i>Cracked</i>	1	98.40 ✓
8	Rear End Panel Buzzer <i>Damaged</i>	1	85.20 ✓
9	Rear End Panel Antenna Sensor <i>xtol new</i>	1	60.10 X
10	Tail Lamp - LH & RH <i>ut</i>	2	949.20 ✓
11	Tail Lamp Lower Apron - LH & RH <i>Repair</i>	2	390.00 X
12	Tailgate <i>Distorted</i>	1	1,100.00 ✓
13	Tailgate Lock <i>Damaged</i>	1	182.50 ✓
14	Tailgate Lock Switch <i>Damaged</i>	1	241.40 ✓
15	Tailgate Outer Garnish <i>Cracked</i>	1	325.00 ✓
16	Tailgate Reflector - LH & RH <i>LH ut, RH cracked</i>	2	826.40 ✓
17	Tailgate Inner Trim Board <i>Debond</i>	1	285.60 ✓
18	Tailgate Glass Moulding <i>new</i>	1	121.00 ✓
19	Honda Logo <i>new</i>	1	35.40 ✓
20	Vezel Emblem <i>new</i>	1	45.90 ✓
21	Hybrid Emblem <i>new</i>	1	75.80 ✓
22	Rear Fender Inner Trim Board <i>Debond LH</i>	2	590.00 ✓ 295.
23	Rear Fender Inner Shield <i>new</i>	2	295.00 X
24	Spare Tyre Panel Top Cover <i>Debond</i>	1	306.60 ✓
25	Rear Exhaust Pipe <i>new</i>	1	598.60 X
26	Rear Exhaust Mounting <i>new</i>	1	28.50 X
	<i>Tailgate weatherstripe. ut</i>		
		135.70 ✓	
			\$ 8,796.80
			(1,759.36)

Less 20%

RE : ESTIMATE FOR ACCIDENT REPAIR SLL7030L (HONDA VEZEL)**\$ 7,037.44****S/NET ITEMS**

1	Rear Number Plate	1	30.00	X
2	Rear Number Plate Holder	1	30.00	X
3	Rear Bumper Clips	1 set	50.00	30
4	Rear Bumper Top Garnish	1	150.00	120
5	Rear Bumper Under Cover Clips	1 set	30.00	✓
6	Reverse Sensor	1	280.00	200
7	Rear End Panel Top Garnish Clips	1 set	20.00	✓
8	Rear End Panel Sealant	1	60.00	✓
9	Tail Lamp Sponge Gasket	2	40.00	✓
10	Tailgate Outer Garnish Clips	1 set	20.00	✓
11	Tailgate Reflector Sponge Gasket	2	40.00	✓
12	Tailgate Inner Trim Board Clips	1 set	30.00	✓
13	Tailgate Glass Sealant	1	60.00	✓
14	Rear Camera	1	480.00	380
15	Rear Fender Inner Trim Board Clips	1 set	60.00	✓
16	Rear Fender Inner Shield Clips	1 set	60.00	X

1,440.00

Total Parts

\$ 8,477.44**LABOUR CHARGE**

1	To knocking & pull out rear portion & renew above parts	\$	1,300.00	800
2	To putty & spray up paint works	\$	1,300.00	900
3	To check wiring system	\$	50.00	30
4	To remove reverse sensor	\$	100.00	50
5	To remove rear camera	\$	100.00	50
6	To spray tuff coat	\$	150.00	80
7	To remove upholstery	\$	150.00	80
8	To transfer tailgate fittings	\$	150.00	80
9	To remove tailgate glass	\$	180.00	120
10	To remove rear exhaust pipe	\$	150.00	X
			\$	3,630.00

RE : ESTIMATE FOR ACCIDENT REPAIR SLL7030L (HONDA VEZEL)

Grand Total

\$ 12,107.44

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 8804.88
h/s: 7050
06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: