

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 18 November 2020

To : LKK

Attn : Bryan

By Fax: 6256-4315

Tel: 97237799

VEHICLE NO : FBE 8086A

Yamaha T135

ACCIDENT DATE: 11 November 2020

Description	Qty	Quotation \$
1 Handle Bar <i>BT</i>	1	165.00 ✓
2 Handle Bar Bracket <i>BT</i>	1	125.00 ✓
3 Steering Cone Bearing <i>SV2</i>	1 set	125.00 X
4 Head Lamp <i>cut</i>	1	320.00 ✓
5 Head Lamp Top Cover <i>broken</i>	1	135.00 ✓
6 Mirror <i>broken / o/s cut H/S NW</i>	2	125.00 ✓ 62.50
7 Brake Lever <i>cut</i>	1	68.00 ✓
8 Meter Cover Rear <i>broken</i>	1	195.00 ✓
9 Leg Shield - Top Cover <i>broken</i>	1	178.00 ✓
10 Leg Shield <i>broken</i>	1	78.00 ✓
11 Front Panel <i>broken</i>	1	135.00 ✓
12 Panel Emblem Logo <i>H/C</i>	1	98.00 ✓
13 Signal L/RH <i>broken</i>	2	150.00 ✓
14 Front Mudguard <i>broken</i>	1	250.00 ✓
15 Fork Tube <i>BT</i>	1 set	480.00 ✓
16 Fork Under Bracket <i>Dam</i>	1	105.00 ✓
17 Radiator Assy <i>NW</i>	1	380.00 X
18 Front Rim <i>distorted</i>	1	325.00 ✓
19 Front Brake Disc <i>NW</i>	1	280.00 X
20 Front Side Panel L/RH <i>distorted / broken</i>	2	250.00 ✓
21 Rear LH Tail Panel <i>NW</i>	1	125.00 X
22 Balancer <i>Dam / H/S distorted o/s NW</i>	1 set	160.00 ✓ 80.00

Sub-Total 4,252.00

Less 10% 425.20

Sub-Total 3,826.80

3199.50

2879.55

LKK Auto Consultants hence notify the Repairer of the following:

- To ensure before repair parts painting
- To display damaged parts during survey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reviewed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature:

Date:

VEHICLE NO : FBE 8086A

Yamaha T135

Nett Items

1	Front number plate <i>missing</i>	15.00 ✓
2	Rear box <i>car M4</i>	450.00 <i>180- X</i>
3	Towing fee <i>M4</i>	40.00 X
4	Remove & replace necessary parts, align & etc	250.00 <i>180-</i>
5	Remove & replace fork assy, fork oil seal, top up fork oil	180.00 <i>80-</i>
6	Supply body decal sticker	<i>505.00</i> 120.00 <i>80-</i>
7	Re-align/adjust front body	250.00 <i>120-</i>
8	Remove & replace rim, brake disc	80.00 <i>30-</i>

Sub-Total 1,385.00

Nett Total 5,211.80

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.

Thank you

17/11/2020 @ 1100hrs

N/A Attached

2/sum 5 days.

Ryan

LKK Auto

3384.55

L/S 2700/-

S9 MOTOR TRADING PTE LTD

:LG

Check MV

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: