

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____ After-Paint: _____
Contacts : _____

Vehicle Nos : **SGZ 7074 X**
Make **Daihatsu Terios**
Model _____
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 695.85	\$ 655.00 695.85
2	Rear bumper side retainer	2	\$ 48.60 89.70	\$ 97.20 179.40
3	Rear bumper reflector	2	\$ 66.25 70.90	\$ 132.50 157.80
4	Rear bumper support bracket	2	\$ 137.40	\$ 274.80
5	Rear number plate lamp	1	\$ 128.50	\$ 128.50
6	Rear bumper tow cover	1	\$ 48.69	\$ 48.69
7	Tailgate	1	\$ 1,340.30	\$ 781.50 1,340.30
8	Tailgate logo	1	\$ 84.60	\$ 84.60
9	Tailgate emblem 'DAIHATSU'	1	\$ 58.00	\$ 58.00
10	Tailgate emblem 'TERIOS'	1	\$ 88.00	\$ 76.70 88.00
11	Tailgate inner trim board	1	\$ 452.30	\$ 215.00 452.30
12	Tailgate weatherstrip	1	\$ 186.60	\$ 186.60
13	Tailgate inner lock	1	\$ 287.90	\$ 287.90
14	Tailgate inner lock sticker	1	\$ 62.30	\$ 62.30
15	Tailgate windscreen moulding	1	\$ 287.00	\$ 128.30 287.00
16	Spare tyre cover inner	1	\$ 1,458.00	\$ 339.30 1,458.00
17	Spare tyre cover outer	1	\$ 1,275.00	\$ 1,275.00
18	Spare tyre cover outer logo	1	\$ 84.60	\$ 84.60
19	Spare tyre bracket	1	\$ 358.10	\$ 358.10
20	Rear end panel	1	\$ 868.00	\$ 480.20 868.00
21	Rear end panel top garnish	1	\$ 210.00	\$ 210.00
22	Rear floor panel top board	1	\$ 580.00	\$ 580.00
23	Rear fender LH	1	\$ 885.30	\$ 885.30
24	Rear fender inner cowl LH	1	\$ 84.00	\$ 84.00
25	Rear fender inner trim board	2	\$ 687.20	\$ 1,374.40
26	Rear fender side glass moulding	1	\$ 110.00	\$ 110.00
27	Taillamp	2	\$ 315.00 433.10	\$ 630.00 866.20
Parts Sub Total :				\$ 12,485.64
15% Discount				\$ 1,872.85
PARTS TOTAL :				\$ 10,612.79

5870.00
@ 15% 880.50
4989.50

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Rear bumper clips	1	\$ 50.00	\$ 50.00
3	Tailgate sealant	1	\$ 100.00	\$ 100.00
4	Tailgate inner trim board clips	1	\$ 50.00	\$ 50.00
5	Tailgate windscreen sealant	1	\$ 120.00	\$ 120.00
6	Tailgate windscreen inner seal	1	\$ 60.00	\$ 60.00
7	Tailgate windscreen primer & cleaner	1	\$ 80.00	\$ 80.00
8	Rear end panel sealant	1	\$ 100.00	\$ 100.00
9	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
10	Rear fender sealant	1	\$ 100.00	\$ 100.00
11	Rear fender side glass sealant	1	\$ 100.00	\$ 100.00
12	Rear fender side glass inner seal	1	\$ 80.00	\$ 80.00
13	Rear fender side glass primer & cleaner	1	\$ 60.00	\$ 60.00
14	Rear fender inner cowlings clips	1	\$ 50.00	\$ 50.00
15	Rear fender inner trim board clips	LH 1	\$ 50.00	\$ 50.00
16	Taillamp clips	2	\$ 50.00	\$ 100.00
17	Taillamp seal	2	\$ 60.00	\$ 120.00
18	Rear number plate w/casing	1	\$ 80.00	\$ 80.00
19	Reverse sensor	2	\$ 250.00	\$ 500.00
SPECIAL NETT TOTAL :				\$ 520.00 1,980.00

Nos.	LABOUR	S\$
1	R&R tailgate componnet	\$ 90.00 150.00
2	R&R tailgate windscreen	\$ 120.00 250.00
3	R&R reverse sensor	\$ 60.00 100.00
4	R&R rear fender side glass	\$ 250.00
5	Check wiring	\$ 50.00 100.00
6	Upholstery	\$ 300.00
7	Panel beat	\$ 800.00 1,400.00
8	Rust proofing	\$ 60.00 200.00
9	Spray painting	\$ 1000.00 1,400.00
LABOUR TOTAL :		\$ 4,150.00

Survey 17/11/2020

1430hrs

TGim Min

Resurvey 18/11/2020

TGim Min

hrs

LABOUR TOTAL : \$ 4,150.00

2,170.00

PARTS TOTAL : \$ 10,612.79

SPECIAL NETT TOTAL : \$ 1,980.00

LABOUR TOTAL : \$ 4,150.00

GRAND TOTAL : \$ 16,742.79

Lump sum repair
Repair days 8

PARTS 4989.50
S/N 520.00
LABOUR 2170.00
7679.50
@ 20% 1535.90
6143.60

L/S 6/100/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TGim Min
25/11/2020