

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 30 Dec 2020

Preliminary Advice

Insured Vehicle No	: SKL1004P		
TP Vehicle No	: SGV5325G	Accident Date	: 12/11/2020
Make	: SUZUKI SWIFT	Assignment Date	: 16/11/2020
Date of Inspection	: 16/11/2020	Est. Duration of Repair	: 5
Inspection At	: Eunost Motor Service (HQ) 1 Kaki Bukit Ave 6, #01-64 AutoBay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,753.42
Revised Amount	:S\$	4,863.77
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,863.77
Lump Sum Repair	:S\$	3,900.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP