

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 31 Jan 2021

ASSESSMENT FOR REPAIR: HONDA CB400 - FBK5719X

Chassis No.:
 Engine No.:

Qty	Description	Estimate
1 pc	• Front fender	\$195.00 ? / CRK
1 pc	• Bracket comp front fender	59 \$118.00 ? / RWS / BT
1 pc	• Front wheel axle	\$115.00 ? / LHS X SVC
1 pc	• Front left fork assy	\$400 \$1,088.00 ? / BT
1 pc	• Front right fork assy	\$400 \$1,088.00 ? / SVC
1 pc	• Front left brake disk	\$350.00 ? / X JV
1 pc	• Front Right brake disk	\$350.00 ? / X JV
1 pc	Front fork steering head crown	\$420.00 ? SVC
1 pc	• Front fork steering stem	\$350 \$450.00 ? / BT
2 pcs	• Steering stem bearing	\$90.00 ? / NEC
1 pc	• Headlamp assembly	\$325.00 ? / SVC
1 pc	• Headlamp bracket	\$225.00 ? / BT
1 pc	Headlamp left holder	\$85.00 ? SVC
1 pc	Headlamp right holder	\$85.00 ? SVC
1 pc	• Steering handle	\$180.00 ? / BT
1 pc	Head fairing	\$155.00 / CRK
1 pc	Meter assy	\$400 \$1,199.00 / CRK
1 set	Throttle cable	\$145.00 / SVC
1 pc	Brake lever	\$95.00 / SVC
1 pc	Right view mirror	\$140.00 / SVC
1 pc	Right balancer	\$45.00 / SVC
1 pc	Front right signal	\$125.00 / SVC
1 pc	Front sport rim	\$750.00
1 set	Crash bar	\$280.00 / DEF
1 pc	Brake pedal	\$115.00 X SVC
1 pc	Right rear signal	\$125.00 / BRK
1 pc	Front right footrest	\$85.00 / SVC
4 pcs	Exhaust slider	\$85.00 / BRK
1 pc	• Exhaust assembly	\$1600 \$1,880.00 ? / DD
		7,119 \$10,396.00
	Less discount 10%	\$1,039.60
		\$9,356.40

Special nett items

1 pc	• Front sport rim	\$600 \$800.00 ? / GRAZED
1 pc	Box rack	\$195.00 ? SVC
1 pc	Top case	\$380 \$480.00 / BRK
1 pc	IU	\$157.00 / SVC
1 pc	Front number plate	\$20.00 / (M1)

1) Towing charges (seperate claim)


1,157 \$100.00 X

SEPARATE

2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00 450
3)	• To replace and balance front and rear wheel rim	\$150.00 70
4)	To knock, straighten chassis & body repair	\$450.00 70
5)	• To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 ?
6)	Spray painting	\$300.00 150
7)	Reset meter	\$120.00 50
Total Estimate		<u>\$13,008.40</u>

Note: The above estimate is subjected to the prevailing GST of 7%

NA2 CLK
4/2/2021 1700
3 DAY
CHECK ITEM PHOTO
AFTER REPAIR PHOTO


For Bike Production Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 9 Feb 2021

SUPPL FOR REPAIR: HONDA CB400 - FBK5719X

Chassis No.:
 Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front left signal	\$125.00 / DEF
1 pc	Meter bracket	\$175.00 / BT
1 pc	Right switch assy	\$215.00 / DEF
1 pc	Right engine cover	\$350 \$395.00 / GRAZED
1 pc	Right engine cover gasket	\$65.00 / NEL
1 pc	Rear right tail cover	\$295.00 / SCR
1 pc	Right side cover	\$145.00
1 pc	Rear right footrest	\$95.00 / SCR
		1,320 \$1,510.00
	Less discount 10%	\$151.00
		\$1,359.00
	<u>Special nett items</u>	
1)	Labour for dismantle and fixing of suppl items	\$100.00 / SO
	Total Estimate	
		\$1,459.00

Note: The above estimate is subjected to the prevailing GST of 7%

PARTS \$8,439.00
 LESS 10% \$7,595.10
 SMENT \$1,157.00
 LABOUR \$ 950.00
 TOTAL \$9,702.10
 LESS L/S 20% \$7,761.68
 L/S TOTAL \$7,750.00 / 3 REPAIR DAYS


 For Bike Production Pte Ltd