

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 31 Jan 2021

ASSESSMENT FOR REPAIR: HONDA CB400 - FBK5719X

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front fender	\$195.00 ?
1 pc	Bracket comp front fender	\$118.00 ?
1 pc	Front wheel axle	\$115.00 ?
1 pc	Front left fork assy	\$1,088.00 ?
1 pc	Front right fork assy	\$1,088.00 ?
1 pc	Front left brake disk	\$350.00 ?
1 pc	Front Right brake disk	\$350.00 ?
1 pc	Front fork steering head crown	\$428.00 ?
1 pc	Front fork steering stem	\$450.00 ?
1 pc	Steering stem bearing	\$90.00 ?
2 pcs	Headlamp assembly	\$325.00 ?
1 pc	Headlamp bracket	\$225.00 ?
1 pc	Headlamp left holder	\$85.00 ?
1 pc	Headlamp right holder	\$85.00 ?
1 pc	Steering handle	\$180.00 ?
1 pc	Head fairing	\$155.00 ✓ CLK
1 pc	Meter assy	\$1,199.00 ✓ CLK
1 set	Throttle cable	\$145.00 ✓ SCR
1 pc	Brake lever	\$95.00 ✓ SCR
1 pc	Right view mirror	\$140.00 ✓ SCR
1 pc	Right balancer	\$45.00 ✓ SCR
1 pc	Front right signal	\$125.00 ✓ SCR
1 pc	Front sport rim	\$750.00
1 set	Crash bar	\$280.00 ✓ DEF
1 pc	Brake pedal	\$115.00 X SVL
1 pc	Right rear signal	\$125.00 ✓ BRK
1 pc	Front right footrest	\$85.00 ✓ SCR
1 pc	Exhaust slider	\$85.00 ✓ BRK
4 pcs	Exhaust assembly	\$1,880.00 ?
1 pc		
		\$10,396.00
	Less discount 10%	\$1,039.60
		\$9,356.40
	<u>Special nett items</u>	
1 pc	Front sport rim	\$800.00 ?
1 pc	Box rack	\$195.00 ?
1 pc	Top case	\$480.00 ✓ BRK
1 pc	IU	\$157.00 ✓ SCR
1 pc	Front number plate	\$20.00 ✓ M13
1)	Towing charges	\$100.00 X

2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$200.00 450
3)	To replace and balance front and rear wheel rim	\$150.00 ?
4)	To knock, straighten chassis & body repair	\$450.00 XNN
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 ?
6)	Spray painting	\$300.00 150
7)	Reset meter	\$120.00 50

Total Estimate

\$13,008.40

Note: The above estimate is subjected to the prevailing GST of 7%

NA2 CLK
4/2/2021 1700
3 Days
CHECK ITEM PHOTO
APRIL REPAIR PHOTO

For Bike Production Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: