



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0868/2020/NS
DATE : 13-Nov-20
WIP : 57580

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

28 days to repair this vehicle.

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : DR PHNG HWEE LENG MERVIN
ADDRESS : 4 HOLLAND HEIGHTS
SINGAPORE 249504
TELEPHONE : HP +65 98625072
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100385096-06
VEHICLE NO : SKG 3998 J
MODEL CODE : AUDI RS 3 SB 2.5 TFSI QU
MODEL YEAR : 29/8/2012
ENGINE NO : CEP 010983
CHASSIS NO : WAUZZZ8P5D1900009
MILEAGE : 49936KM
DATE IN : 12-Nov-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Nov-20
PLACE OF ACCIDENT : ALONG QUEENSWAY EXIT TO JALAN
BUKIT MERAH

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKG 3998 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$ 800.00	
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	\$ 360.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY.	S/N \$ 1,800.00	\$ 1,800.00
SUB TOTAL LABOUR CHARGES		: \$ 4,160.00	\$ 2,160.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKG 3998 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		b/f		\$ 2,160.00
5	TO REMOVE AND REINSTALL CENTRE CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	S/N \$	3,200.00	\$ 3,200.00
6	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$	1,800.00	\$ 1,800.00
7	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	280.00	\$ 280.00
8	TO PLACE VEHICLE ON CAR O-LINER.	S/N \$	2,400.00	
SUB TOTAL LABOUR CHARGES		:	\$ 7,680.00	\$ 7,440.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKG 3998 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		b/f	\$	7,440.00
9	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS, RHS FRONT DOOR AND RHS SILL PANEL TRIM. CUT OUT AND REWELD RHS LOWER A-PILLAR AND RHS SILL PANEL. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	9,800.00	\$ 4,000.00
10	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, RHS LOWER A-PILLAR, RHS SILL PANEL, RHS SILL PANEL TRIM, DOOR ENTRANCE, RHS FRONT DOOR, RHS WING MIRROR COVER AND DOOR COVER. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	\$	7,900.00	\$ 4,150.00
11	TO RENEW BOTH FRONT RIMS. TO CARRY OUT PRE AND POST REPAIR WHEEL ALIGNMENT CHECK.	S/N \$	560.00	\$ 320.00
12	TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 384.00
SUB TOTAL LABOUR CHARGES		:	\$ 30,484.00	\$ 16,294.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 3998 J

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
1	FRONT BUMPER		\$	5,789.00	\$ 4,631.20
2	FRONT BUMPER FIXING PARTS		\$	258.00	
3	FRONT BUMPER CARRIER		\$	1,145.00	
4	FRONT BUMPER SHOCK ABSORBER - LH		\$	342.00	
5	FRONT BUMPER GUIDE SECTION - LH/RH	2	\$	624.00	\$ 249.20
6	RADIATOR GRILLE		\$	4,201.00	\$ 3,360.80
7	RADIATOR GRILLE CLOSING ELEMENT		\$	647.00	
8	RS3 INSCRIPTION		\$	122.00	\$ 97.60
9	FRONT BUMPER AIR GUIDE GRILLE - LH/RH	2	\$	832.00	
10	FRONT BUMPER END CAP		\$	268.00	
11	FRONT BUMPER TRIM STRIPS - LH/RH	2	\$	850.00	
12	FRONT BUMPER SPOILER - LOWER CENTRE		\$	1,411.00	
13	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$	397.00	
14	FRONT BUMPER FOAM FILLER PIECE		\$	268.00	
15	SPRING SHACKLE		\$	66.00	
16	SIGNAL HORN - LOW/HIGH TONE	2	\$	446.00	
17	FRONT FENDER - LH/RH	2	\$	12,602.00	\$ 10,081.60
18	FRONT FENDER BRACE - LH FRONT		\$	53.00	\$ 42.24
19	FRONT FENDER BRACKET - LH/RH LOWER	2	\$	162.00	\$ 128.80
20	FRONT FENDER CLOSING ELEMENT - LH/RH	2	\$	184.00	\$ 147.04
SUB TOTAL SPARE PARTS		:	\$	30,667.00	\$ 18,738.48

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 3998 J

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
	<i>c/f</i>			\$	18,738.48
21	WHEEL HOUSING LINER - LH/RH INNER	2	\$	586.00	\$ 468.00
22	WHEEL HOUSING LINER - LH/RH OUTER	2	\$	586.00	\$ 468.00
23	WHEEL SPOILER - LH/RH	2	\$	134.00	\$ 53.44
24	WHEEL HOUSING SOUND ABSORBER - LH/RH	2	\$	212.00	
25	BONNET		\$	2,373.00	
26	BONNET LID HINGE - LH/RH	2	\$	114.00	
27	BONNET CATCH HOOK		\$	92.00	
28	BONNET LID LOCK		\$	212.00	
29	BONNET LOCK COVER - UPPER FRONT		\$	51.00	
30	HEADLIGHT - LH/RH	2	\$	4,556.00	\$ 1,822.40
31	GAS DISCHARGE LAMP		\$	408.00	
32	GAS DISCHARGE LAMP CONTROL UNIT		\$	1,084.00	
33	CORNERING LIGHT POWER MODULE		\$	1,043.00	
34	HEADLIGHT HOSE - LH		\$	12.00	
35	FLAT CONTACT HOUSING		\$	30.00	\$ 23.60
36	LIFT CYLINDER - LH		\$	201.00	\$ 160.80
37	LIFT CYLINDER HOSE	5	\$	184.00	
38	WASH WATER RESERVOIR		\$	170.00	
39	LOCK CARRIER		\$	2,289.00	
40	AIRCON CONDENSER		\$	1,079.00	
SUB TOTAL SPARE PARTS		:	\$	15,416.00	\$ 21,734.72



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 3998 J

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		S/NETT	REMARKS
	c/f			\$		21,734.72
41 AIRCON STICKER		NEC	\$	18.00	\$	13.84
42 ADDITIONAL RADIATOR			\$	1,874.00		
43 ADDITIONAL RADIATOR BRACKET - LH/RH		2	\$	426.00		
44 READY MIX COOLANT			\$	91.00		
45 RADIATOR AIR GUIDE - LH			\$	39.00		
46 RADIATOR AIR GUIDE - LH OUTER			\$	78.00		
47 FRONT DOOR - RH			\$	2,176.00	\$	1,740.80
48 FRONT DOOR HINGE - RH LOWER			\$	237.00	\$	189.60
49 FRONT DOOR HINGE - RH UPPER			\$	71.00		
50 DOOR HINGE RETAINING PLATE			\$	13.00		
51 FRONT DOOR SIDE REINFORCEMENT			\$	157.00		
52 FRONT DOOR INNER SEAL			\$	250.00		
53 TYRE PRESSURE DATA PLATE			\$	20.00	\$	15.36
54 EXTERIOR MIRROR MOUNTING - RH			\$	1,013.00		
55 MIRROR CAP - RH			\$	1,282.00	\$	1,025.60
56 MIRROR GLASS - RH			\$	1,644.00		
57 TURN SIGNAL INDICATOR			\$	99.00		
58 FRONT DOOR COVER - RH			\$	326.00	\$	260.80
59 FRONT DOOR PROTECTIVE STRIP - RH			\$	201.00	\$	160.80
60 SIDE MEMBER TRIM - RH			\$	1,029.00	\$	823.20
SUB TOTAL SPARE PARTS		:	\$	11,044.00	\$	25,964.72

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 3998 J

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
	<i>c/f</i>		\$	25,964.72
61	SIDE MEMBER TRIM CAP - RH	\$	164.00	\$ 131.20
62	A-PILLAR - RH	\$	1,120.00	\$ 896.00
63	SILL TRIM STRIP - RH OUTER	\$	679.00	
64	SILL TRIM STRIP - RH INNER	\$	187.00	
65	DATA TAG	\$	457.00	
66	NOISE INSULATION	\$	746.00	
67	UNDERBODY TRIM	\$	245.00	
68	FRONT ALUMINIUM RIM - LH/RH	2 \$	2,728.00	\$ 2,182.40
69	TRACK CONTROL ARM - LH	\$	371.00	
70	WHEEL BEARING HOUSING - LH	\$	666.00	
71	WHEEL BEARING	\$	949.00	\$ 759.20
72	GUIDE JOINT - LH	\$	136.00	\$ 108.40
73	TIE ROD END - LH	\$	122.00	
74	STONE CHIP	S/N \$	180.00	
75	CAVITY WAX	S/N \$	140.00	
76	ACRYLIC SEALANT	S/N \$	180.00	
77	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
78	SUPPLEMENTARY	\$	117.00	\$ 93.60
79	SUNDRIES	\$	400.00	\$ 445.12
TOTAL SPARE PARTS		:	\$ 66,774.00	\$ 30,640.64
TOTAL LABOUR CHARGES		:	\$ 30,484.00	\$ 16,294.00
GRAND TOTAL		:	\$ 97,258.00	\$ 46,934.64

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No. PA/OD/0868/2020/NS
Date 3-Dec-20
Service Advisor CHANG
Pages 1 of 1
Regn No SKG 3998 J
Model No AUDI RS3 SB 2.5 TFSI QU

Quantity	Description	Unit Price	Amount
Parts			
1	HEADLIGHT MOUNTING - LH	\$ 117.00	\$ 93.60
GRAND TOTAL		\$ 117.00	\$ 93.60

For Premium Automobiles Pte Ltd

Authorised Signature