

# SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TPA LG.  
Jasper

16 November 2020

## QUOTATION FOR ACCIDENT REPAIR OF SLK5947K HONDA FIT

### THIRD PARTY INSURER: AIG INSURANCE

S/No.	Parts	Qty	Amount (\$)
1.	Rear tailgate <i>Dishled</i>	1	\$ 967.60 <i>845</i>
2.	Rear windscreen moulding <i>new</i>	1	\$ 120.40 ✓
3.	Rear tailgate "logo" emblem <i>new</i>	1	\$ 35.00 ✓
4.	Rear tailgate "FIT" emblem <i>new</i>	1	\$ 38.00 ✓
5.	Rear tailgate no plate lamp L/R <i>new</i>	2	32.80 \$ 65.60 +
6.	Rear tailgate no plate lamp garnish <i>could</i>	1	\$ 185.20 ✓
7.	Rear tailgate weather strip <i>nt</i>	1	\$ 142.30 ✓
8.	Rear tailgate damper L/R <i>new</i>	2	136.30 \$ 272.60 +
9.	Rear tailgate mechanism lock <i>new</i>	1	<del>\$ 263.90</del> <i>189</i>
10.	Rear tailgate lock striker <i>new</i>	1	\$ 55.00 +
11.	Rear tailgate inner trim <i>could</i>	1	\$ 296.30 ✓
12.	Rear tailgate inner trim clip <i>new</i>	12	4.50 \$ 54.00 <i>30</i>
13.	Rear taillamp RH <i>could</i>	1	<del>\$ 348.20</del> <i>288</i>
14.	Rear taillamp bracket RH <i>new</i>	1	\$ 55.00 +
15.	Rear taillamp panel RH <i>Dented</i>	1	\$ 230.80 ✓
16.	Rear bumper <i>Dented</i>	1	<del>\$ 660.90</del> <i>485</i>
17.	Rear bumper side retainer L/R <i>new</i>	2	45.90 \$ 91.80 ✓
18.	Rear bumper towing cover <i>Dishled</i>	1	\$ 59.20 ✓
19.	Rear end panel <i>Dented</i>	1	\$ 386.50 ✓
20.	Rear end panel garnish <i>de led</i>	1	\$ 140.80 ✓
21.	Rear spare tyre panel <i>Dishled</i>	1	\$ 737.00 ✓
22.	Rear spare tyre panel top sponge <i>de led</i>	1	\$ 243.80 ✓
23.	Rear spare type panel top cover <i>Dented</i>	1	\$ 282.80 ✓
24.	Rear exhaust heat shield <i>could</i>	1	\$ 168.90 ✓
25.	Rear exhaust rubber mounting <i>new</i>	2	20.80 \$ 41.60 +
26.	Rear sub chassis RH <i>Repair</i>	1	\$ 380.50 +
27.	Rear sub chassis top panel RH <i>Repair</i>	1	\$ 157.80 +
28.	Rear fender RH <i>Repair</i>	1	\$ 820.60 +
29.	Rear fender air vent RH <i>new</i>	1	\$ 76.80 +
30.	Rear fender inner trim RH <i>could</i>	1	\$ 335.60 ✓
31.	Rear fender inner trim clip RH <i>new</i>	12	4.50 <del>\$ 54.00</del> <i>30</i>
Subtotal before discount			\$ 7768.50
Discount 20%			<del>\$ 1553.70</del>
<b>Subtotal 1</b>			<b>\$ 6214.80</b>

5 371.40

4297.12

# SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

16 November 2020

## QUOTATION FOR ACCIDENT REPAIR OF SLK5947K HONDA FIT

### THIRD PARTY INSURER: AIG INSURANCE

<u>S/Nett.</u>	<u>Parts</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Rear number plate <i>3 new</i>	1	\$ 25 +
2.	Rear number plate garnish	1	\$ 50 +
3.	Rear reverse sensor <i>Dead</i>	1	<del>\$ 350</del> - 200
4.	Rear reverse camera <i>new</i>	1	\$ 400 +
5.	Rear bumper clip <i>new</i>	1	\$ 30 -
6.	Rear end panel sealant <i>new</i>	1	\$ 50 -
7.	Rear spare tyre panel sealant <i>new</i>	1	\$ 50 -
8.	Rear exhaust silencer (HKS) <i>Best</i>	1	<del>\$ 1500</del> 600
9.	Rear fender windscreen sealant <i>new</i>	1	\$ 50 +
10.	Rear windscreen sealant <i>new</i>	1	\$ 50 -
<b>Subtotal 2</b>			<u>\$ 2555</u>

1380.

### Rear Labour

To check wirings.	\$ 80	<i>30</i>
To transfer tailgate component parts to new boot	\$ 100	<i>80</i>
To remove and reinstall rear windscreen for necessary repair.	\$ 150	<i>125</i>
To remove and reinstall rear fender glass for necessary repair	\$ 120	<i>4</i>
To remove, replace and reinstall rear reverse sensor	\$ 80	<i>50</i>
To remove, replace and reinstall rear reverse camera	\$ 80	<i>50</i>
To remove, and reinstall exhaust silencer for necessary	\$ 120	<i>80</i>
To remove, reinstall, cushion seat, trim garnish, trim liner carpet	\$ 120	<i>60</i>
To spray anti-rust coating on new and affected panels	\$ 150	<i>80</i>
To straighten, repair, realign on affected area and replace damaged parts	\$ 1200	<i>1000</i>
To spray painting on affected area	\$ 1200	<i>1000</i>
<b>Total Labour Cost</b>	<u>\$ 3400</u>	

2550

Total Cost Of Repairs (Total cost of parts + Total labour cost)

**\$12169.80**

*Adrian G  
w/s 17/11/20*

*09 Days*

*Total: 8227.12  
w/s: G.S/K*