



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2100389  
INV Date 18/01/2021  
Reference CC4/LPC20012603/Uga3q2  
Code LPC2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SJH 3822P  
Insured Veh. GBD 2924B  
Claim No. 20/20/20/VC05/033901  
Policy No. Z20VC05005042  
Accident Date 13/11/2020  
Inspection Date 16/11/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC20012603/Uga3q2

Date: 18/01/2021

Code: LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBD 2924B	<b>Veh. Inspected</b>	SJH 3822P
<b>Policy No.</b>	Z20VC05005042	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	20/20/20/VC05/033901	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	Gerald Poh	<b>Assign Date</b>	16/11/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	mitsubishi attrage (A)	<b>c.c</b>	1193
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	MMBSTA13AJH000800	<b>Colour</b>	WHITE
<b>Odometer</b>	31166 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	185/55 R15	BRIDGESTONE	7 mm
<b>L/H Front Tyre</b>	185/55 R15	BRIDGESTONE	7 mm
<b>R/H Rear Tyre</b>	185/55 R15	BRIDGESTONE	7 mm
<b>L/H Rear Tyre</b>	185/55 R15	BRIDGESTONE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	13/11/2020	<b>Inspection Date</b>	16/11/2020
<b>Survey held at</b>	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 3822P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOT (N)	BURST	765.00	765.00
2	REAR BOOT HINGE RH/LH @\$185.00 (N)	BENT / TWISTED	370.00	370.00
1	REAR BOOT RUBBER (N)	TWISTED	193.00	157.00
1	REAR BOOT STOPPER RH (N)	MISSING	10.00	10.00
1	REAR BOOT LOCK (N)	TWISTED	228.00	218.00
1	REAR BOOT LOCK CATCH (N)	NOT NECESSARY	21.00	-
1	REAR BOOT LOCK KEYLESS SMART (N)	NOT NECESSARY	179.00	-
1	REAR BOOT LOCK KEYLESS BUZZLE (N)	NOT NECESSARY	194.00	-
2	REAR BOOT NUMBER PLATE LAMP @\$48.00 (N)	NOT NECESSARY	96.00	-
1	REAR BOOT CHROME MOULDING (N)	CRACKED	336.00	336.00
1	REAR BOOT EMBLEM LOGO (N)	NECESSARY	41.00	41.00
1	REAR BOOT EMBLEM 'ATTRAGE' (N)	NECESSARY	38.00	21.00
1	REAR BOOT EMBLEM 'MIVEC' (N)	NECESSARY	48.00	48.00
2	REAR TAILLAMP RH/LH @\$266.00 (N)	CRACKED	532.00	532.00
2	REAR TAILLAMP PANEL HOUSING RH/LH @\$157.00 (N)	N/S TO REPAIR SEE LABOUR / O/S BENT	314.00	157.00
1	REAR BUMPER (N)	DISTORTED	659.00	659.00
2	REAR BUMPER REFLECTOR RH/LH @\$28.00 (N)	O/S CRACKED	56.00	28.00
2	REAR BUMPER SIDE RETAINER RH/LH @\$32.00 (N)	O/S BENT	64.00	32.00
1	REAR EXHAUST BOX (N)	DENTED / BENT	571.00	571.00
3	REAR EXHAUST BOX MOUNTING @\$24.00 (N)	NOT NECESSARY	72.00	-
1	REAR END PANEL (N)	BADLY DENTED	412.00	412.00
1	REAR END PANEL GARNISH (N)	TWISTED	92.00	66.00
1	REAR END PANEL AIR VENT (N)	CRACKED	36.00	36.00
1	REAR END PANEL AIR VENT GARNISH (N)	CRACKED	32.00	32.00
1	REAR SPARE TYRE PANEL (N)	CRUMPLED / BUCKLE	987.00	956.00
1	REAR SPARE TYRE PANEL LOWER CROSSMEMBER (N)	BUCKLED	255.00	255.00
1	REAR SPARE TYRE PANEL CARDBOARD (N)	TORN	197.00	195.00
1	REAR SPARE TYRE PANEL SCREW CARRIER (N)	NOT NECESSARY	39.00	-

Report Ref No. CC4/LPC20012603/Uga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CHASSIS MEMBER RH (N)	TO REPAIR SEE LABOUR	211.00	-
2	REAR FENDER RH/LH @\$725.00 (N)	N/S TO REPAIR SEE LABOUR / O/S BUCKLE	1,450.00	725.00
2	REAR FENDER INNER TRIM RH/LH @\$178.00 (N)	O/S DISTORTED	356.00	178.00
1	REAR FENDER LOWER SHIELD RH (N)	DEFORMED / TWISTED	48.00	48.00
1	REAR DOOR INNER LOCK RH (N)	NOT NECESSARY	290.00	-
	LESS 10% DISCOUNT		-919.20	-684.80
			8,272.80	6,163.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WINDSCREEN SPONGE TAPE (SN)	NECESSARY	20.00	20.00
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR INNER TRIM CLIP (SN)	NECESSARY	45.00	40.00
1	REAR BOOT TOP SPOILER (SN)	BROKEN	480.00	380.00
1	SET REAR NUMBER PLATE WITH CASING (SN)	BENT	50.00	40.00
1	SET REVERSE CAMERA (SN)	SHORTED	350.00	300.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			1,340.00	1,055.00
	<b><u>LABOUR</u></b>			
	TO KNOCK OUT DENT ,CUT/WELD REAR PANEL ,REAR SPARE TYRE PANEL ,REAR CHASSIS RH ,REAR FENDER RH /LH AND REPLACE ACCIDENT PARTS.INCLUDING OF THE REPAIR OF REAR TAILLAMP PANEL HOUSING LH,REAR CHASSIS MEMBER RH AND REAR FENDER LH.		2,400.00	2,000.00
	TO SPRAY PAINTING ON ACCIDENT PORTION .		1,350.00	1,200.00
	TO CHECK WIRING .		30.00	30.00
	TO REMOVE ,REFIX REAR WINDSCREEN .		120.00	120.00
	TO REMOVE,REFIX CUSHION AND INNER TRIM .		120.00	80.00
	TO REMOVE,REPLACE REVERSE CAMERA AND REVERSE SENSOR .		150.00	50.00
	TO REMOVE ,REPLACE REAR EXHAUST BOX.		120.00	60.00
	TO REMOVE ,REFIX FUEL TANK .		120.00	60.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF-KOTE.		150.00	100.00
			4,560.00	3,700.00
<b>GRAND TOTAL</b>			<b>14,172.80</b>	<b>10,918.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>8,700.00</b>

Report Ref No. CC4/LPC20012603/Uga3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 3822P

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 3822P

RE-INSPECTION

