

# WATERS AUTOMOTIVE PTE. LTD.

*Uth Cecilia*

1111 AVENUE 6 #02-47  
SINGAPORE 417883  
5521 / 65095524 Fax : 6509 5523

*Not Authorized  
16/11/20  
2/s #8700/  
12 days*

## ESTIMATE

DATE : 16/11/2020  
VEHICLE NO : SJH3822P  
MAKE/MODEL : MIT ATTRAGE  
ACC DATE : 13/11/2020

Motor Claims Dept.  
LONPAC INSURANCE BHD  
100 BEACH ROAD  
#19-00 SHAW PLAZA  
SINGAPORE 189702  
**GBD2924B**

PARTICULAR	UNIT PRICE		AMOUNT	
		SS		SS
1 REAR BOOT <i>Buc</i>		\$ 765.00	\$	765.00 ✓
2 REAR BOOT HINGE RH / LH <i>2 set / 2w1</i>		\$ 185.00	\$	370.00 ✓
3 REAR BOOT RUBBER <i>7m1</i>	157	\$ 193.00	\$	193.00 ✓
4 REAR BOOT STOPPER RH <i>MIS</i>		\$ 10.00	\$	10.00 ✓
5 REAR BOOT LOCK <i>7m1</i>	218	\$ 228.00	\$	228.00 ✓
6 REAR BOOT LOCK CATCH <i>u7</i>		\$ 21.00	\$	21.00 X
7 REAR BOOT LOCK KEYLESS SMART <i>11</i>		\$ 179.00	\$	179.00 X
8 REAR BOOT LOCK KEYLESS BUZZLE <i>11</i>		\$ 194.00	\$	194.00 X
9 REAR BOOT NUMBER PLATE LAMP <i>11</i>		\$ 48.00	\$	96.00 X
10 REAR BOOT CHROME MOULDING <i>one</i>		\$ 336.00	\$	336.00 ✓
11 REAR BOOT EMBLEM LOGO <i>new</i>		\$ 41.00	\$	41.00 ✓
12 REAR BOOT EMBLEM 'ATTRAGE' <i>new</i>	21	\$ 38.00	\$	38.00 ✓
13 REAR BOOT EMBLEM 'MIVEC' <i>new</i>		\$ 48.00	\$	48.00 ✓
14 REAR TAILLAMP RH / LH <i>one</i>		\$ 266.00	\$	532.00 ✓
15 REAR TAILLAMP PANEL HOUSING RH / LH <i>1 set / 1 set</i>		\$ 157.00	\$	314.00 1pc
16 REAR BUMPER <i>dis</i>		\$ 659.00	\$	659.00 ✓
17 REAR BUMPER REFLECTOR RH / LH <i>ols cro</i>		\$ 28.00	\$	56.00 1pc
18 REAR BUMPER SIDE RETAINER RH / LH <i>ols bent</i>		\$ 32.00	\$	64.00 1pc
19 REAR EXHAUST BOX <i>dis/bent</i>		\$ 571.00	\$	571.00 ✓
20 REAR EXHAUST BOX MOUNTING <i>u7</i>		\$ 24.00	\$	72.00 X
21 REAR END PANEL <i>Body</i>		\$ 412.00	\$	412.00 ✓
22 REAR END PANEL GARNISH <i>7m1</i>	66	\$ 92.00	\$	92.00 ✓
23 REAR END PANEL AIR VENT <i>one</i>		\$ 36.00	\$	36.00 ✓
24 REAR END PANEL AIR VENT GARNISH <i>one</i>		\$ 32.00	\$	32.00 ✓
25 REAR SPARE TYRE PANEL <i>crumpled / Buc 95B</i>		\$ 987.00	\$	987.00 ✓
26 REAR SPARE TYRE PANEL LOWER CROSSMEMBER <i>Buc</i>		\$ 255.00	\$	255.00 ✓
27 REAR SPARE TYRE PANEL CARDBOARD <i>7m1</i>	195	\$ 197.00	\$	197.00 ✓
28 REAR SPARE TYRE PANEL SCREW CARRIER <i>11</i>		\$ 39.00	\$	39.00 X
29 REAR CHASSIS MEMBER RH <i>R</i>		\$ 211.00	\$	211.00 X
30 REAR FENDER RH / LH <i>M/S R ols Buc</i>		\$ 725.00	\$	1,450.00 1pc
31 REAR FENDER INNER TRIM RH / LH <i>ols dis</i>		\$ 178.00	\$	356.00 1pc
32 REAR FENDER LOWER SHIELD RH <i>dis/bent</i>		\$ 48.00	\$	48.00 ✓
33 REAR DOOR INNER LOCK RH <i>u7</i>		\$ 290.00	\$	290.00 X
			\$	9,192.00
		LESS -10%	\$	919.20
		TOTAL	\$	8,172.80

# LEE BROTHERS AUTOMOTIVE PTE. LTD.

	PARTICULAR	UNIT PRICE	AMOUNT
			S\$
	<b>SPECIAL NETT ITEMS</b>		
1	1 REAR WINDSCREEN SPONGE TAPE <i>nee</i>	\$	20.00 ✓
2	1SET REAR WINDSCREEN SEALANT <i>nee</i>	\$	80.00 40
3	1SET REAR INNER TRIM CLIP <i>nee</i>	\$	45.00 40
4	1 REAR BOOT TOP SPOILER <i>bro</i>	\$	480.00 380
5	1SET REAR NUMBER PLATE WITH CASING <i>sent</i>	\$	50.00 40
6	<i>set</i> REVERSE CAMERA <i>shuph</i>	\$	350.00 300
7	1SET REAR BUMPER CLIPS <i>nee</i>	\$	35.00 ✓
8	1SET REAR BUMPER REVERSE SENSOR <i>shuph</i>	\$	280.00 200
		\$	1,340.00
			<i>1057</i>

<b>LABOUR CHARGES :</b>			
1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, REAR SPARE TYRE PANEL, REAR CHASSIS RH, REAR FENDER RH / LH AND REPLACE ACCIDENT PARTS	<i>2000</i>	\$ 2,400.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	<i>1200</i>	\$ 1,350.00
3	TO CHECK WIRING		\$ 30.00 ✓
4	TO REMOVE ,REFIX REAR WINDSCREEN		\$ 120.00 ✓
5	TO REMOVE, REFIX CUSHION AND INNER TRIM	<i>80</i>	\$ 120.00
6	TO REMOVE, REPLACE REVERSE CAMERA AND REVERSE SENSOR	<i>50</i>	\$ 150.00
8	TO REMOVE, REPLACE REAR EXHAUST BOX	<i>60</i>	\$ 120.00
9	TO REMOVE, REFIX FUEL TANK	<i>60</i>	\$ 120.00
10	TO TUFF - KOTE	<i>100</i>	\$ 150.00
			\$ 4,560.00
			<i>3700</i>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*P-6848*  
*10%*  
*P-6163-20*  
*SIN-1055*  
*L-3700*  
*69682*  
*8734*