

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 56570**
Date Estimated : **16/11/2020**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -

Tang Hui Ping Gyneth
15 Evelyn Road
#14-02

Singapore 309311

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGD83G	WBA6A02010DZ11822	17/10/2014	640iA GC	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper, front center air duct and bonnet including to knock out dented are a caused by the accident	2,125.00		2,125.00
To respray front bumper and bonnet	2,102.00		2,102.00
To carry out body cavity preservation. (Per panel).	100.00		100.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	150.00		150.00
Sundries	150.00		150.00
# To replace air con condensor and carry out repair job including to vacuum system, top up gas and check for leak	850.00		850.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET	1.35	2.00		2.70
BONNET	2,844.20	1.00		2,844.20
FRT BUMPER TRIM PRIMED (PDC)	1,565.90	1.00		1,565.90
# GRILLE AIR INTAKE CENTER	118.80	1.00		118.80
FRT LH GRILLE	166.10	1.00		166.10
FRT RH GRILLE	166.10	1.00		166.10
BMW EMBLEM	71.60	1.00		71.60
FRT AIR DUCT	350.45	1.00		350.45
SEAL ENGINE BONNET FRT	33.20	1.00		33.20
SUPPORT SEAL REAR RH	255.10	1.00		255.10
# CONDENSER AIR CONDITIONING	1,033.60	1.00		1,033.60

SUPPLEMENTARY ITEMS

Total Labour :	5,477.00
Total Parts :	6,607.75
Total Labour & Parts :	12,084.75
Deduction for Excess :	0.00
Total Repair Costs less Excess:	12,084.75
GST @7%:	845.93
Grand Total :	12,930.68



Supplementary

Estimate No. : **b1 56570**
Date Estimated : **16/11/2020**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -

Tang Hui Ping Gyneth
15 Evelyn Road
#14-02

Singapore 309311

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGD83G	WBA6A02010DZ11822	17/10/2014	640iA GC	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace air con condensor and carry out repair job including to vacuum system, top up gas and check for leak	850.00		850.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET	1.35	2.00		2.70
# GRILLE AIR INTAKE CENTER	118.80	1.00		118.80
# CONDENSER AIR CONDITIONING	1,033.60	1.00		1,033.60

SUPPLEMENTARY ITEMS

Total Labour :	850.00
Total Parts :	1,155.10
Total Labour & Parts :	2,005.10