

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Xiao Tony.

Quotation

DATE : 19.11.2020
 VEH NO : SLB7219M
 MODEL : Mitsubishi Lancer
 D O A : 13.11.2020
 YR REF : SMP9577E

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLB7219M (MITSUBISHI LANCER)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp - LH & RH <i>Not m</i>	2	64.00 X
2	Rear Bumper <i>Distorted</i>	1	855.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>m</i>	2	70.00 ✓
4	Rear Bumper Beam <i>Bent</i>	1	169.00 ✓
5	Rear Bumper Reinforcement <i>Bent</i>	1	254.00 ✓
6	Rear Bumper Reflector - LH & RH <i>LH cracked</i>	2	76.00 38. ✓
7	Rear Bumper Tow Cover <i>Not m</i>	1	27.00 X
8	Rear End Panel <i>Dented</i>	1	506.00 ✓
9	Rear End Panel Top Garnish <i>crack d</i>	1	145.00 ✓
10	Rear End Panel Smart Entry Antenna <i>Damaged</i>	1	142.00 ✓
11	Tail Lamp - LH & RH <i>Not m</i>	2	808.00 X
12	Tail Lamp Panel - LH & RH <i>Not m</i>	2	358.00 X
13	Bootlid <i>Buckled</i>	1	755.00 ✓
14	Bootlid Lock <i>Damaged</i>	1	155.00 ✓
15	Bootlid Weatherstripe <i>cut</i>	1	161.00 ✓
16	Bootlid Hinge <i>Not m</i>	2	190.00 X
17	Mitsubishi Logo	1	58.00 ✓
18	Lancer Emblem <i>Not m</i>	1	55.00 ✓
19	Mivec Emblem	1	48.00 ✓
20	Cycle and Carriage Logo <i>Not m</i>	1	56.00 ✓
21	Spare Tyre Panel Top Cover <i>Not m</i>	1	195.00 X
22	Rear Fender Inner Trim - LH <i>Not m</i>	1	223.00 ✓

3680

3321

Les: 10%

5,370.00
 (537)
 \$ 4833

S/NETT ITEMS

RE : ESTIMATE FOR ACCIDENT REPAIR SLB7219M (MITSUBISHI LANCER)

1	Rear Number Plate <i>Best</i>	1	\$	30.00 ✓
2	Rear Number Plate Holder <i>Behind</i>	1	\$	30.00 ✓
3	Rear Bumper Clips <i>in</i>	1 set	\$	50.00 <i>30</i>
4	Reverse Sensor <i>Damaged</i>	1	\$	280.00 <i>280</i>
5	Rear Camera <i>Damaged</i>		\$	480.00 <i>380</i>
6	Rear End Panel Top Garnish Clips <i>in</i>	1 set	\$	20.00 ✓
7	Rear End Panel Sealant <i>in</i>	1 set	\$	60.00 ✓
8	Rear Fender Inner Trim Clips - LH <i>in</i>	1 set	\$	30.00 ✓
			\$	980.00

Total Parts

\$

5813

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 <i>800</i>
2	To putty & spray up paint works	\$	1,200.00 <i>800</i>
3	To check wiring	\$	50.00 <i>30</i>
4	To remove reverse sensor	\$	100.00 <i>50</i>
5	To remove rear camera	\$	100.00 <i>50</i>
6	To remove upholstery	\$	150.00 <i>80</i>
7	To transfer bootlid fittings	\$	150.00 <i>60</i>

Total Labour

\$

2,950.00

Grand Total

\$

8763

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5971
L/S: 4750
06 Days.