



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2102376

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 08/04/2021
Reference CC4/FCI20012615/Ara3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJQ 8428P
Insured Veh. SHB 4076A
Claim No. D20004639MFSH
Policy No. D-20094922MFSH
Accident Date 10/11/2020
Inspection Date 16/11/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20012615/Ara3q2	
			Date: 08/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4076A	Veh. Inspected	SJQ 8428P	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20004639MFSH	Excess (\$)	0.00	
Assign From	CHRIS LIM	Assign Date	16/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053HY9305111248	Colour	SILVER	
Odometer	304492 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	FALKEN	6 mm	
L/H Front Tyre	195/55 R15	FALKEN	6 mm	
R/H Rear Tyre	195/55 R15	FALKEN	6 mm	
L/H Rear Tyre	195/55 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/11/2020	Inspection Date	16/11/2020	
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 8428P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TORN	408.60	408.60
1	FRONT BUMPER SIDE HOLDER @\$133.20	N/S NECESSARY	266.40	35.00
1	SET FRONT BUMPER CLIP	NECESSARY	60.00	30.00
1	FRONT LH HEADLAMP	CUT	420.10	420.10
1	FRONT LH FENDER	DENTED	639.20	545.00
1	FRONT LH FENDER INNER SHIELD	NOT NECESSARY	189.70	-
1	SET FRONT LH FENDER INNER SHIELD CLIPS	NOT NECESSARY	60.00	-
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	1,399.20	-
1	FRONT LH DOOR PROTECTOR	CUT	189.50	189.50
1	FRONT LH DOOR SIDE MIRROR }	DAMAGED	2,170.10	980.00
1	FRONT LH DOOR SIDE MIRROR HOUSING }		-	-
1	FRONT LH DOOR SIDE MIRROR COVER	TO REPAIR SEE LABOUR	188.80	-
1	SET FRONT LH DOOR BLACK STICKER	NOT NECESSARY	188.60	-
1	FRONT LH SHOCK ABSORBER	NOT NECESSARY	387.80	-
1	FRONT LH KNUCKLE ARM	DAMAGED	486.90	486.90
1	FRONT LH KNUCKLE ARM BEARING	NECESSARY	131.40	131.40
1	FRONT LH LOWER ARM	BENT	871.50	330.00
1	FRONT LH DRIVE SHAFT	NOT NECESSARY	1,610.10	-
1	REAR LH DOOR PROTECTOR	NOT NECESSARY	188.60	-
	LESS 25% DISCOUNT		-2,464.13	-889.13
			7,392.37	2,667.37
<u>SPECIAL NETT ITEMS</u>				
1	FRONT LH SPORT RIM (SN)	CUT	850.00	500.00
1	FRONT LH TYRE (SN)	NOT NECESSARY	380.00	-
			1,230.00	500.00
<u>LABOUR</u>				
	TO CHECK WHEEL ALIGNMENT .		100.00	80.00
	REMOVE & REINSTALL FRONT LH SUSPENSION .		400.00	200.00

Report Ref No. CC4/FCI20012615/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE ,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF FRONT LH DOOR AND FRONT LH DOOR SIDE MIRROR COVER . RESPRAY PAINTING .		1,100.00	500.00
			1,200.00	800.00
			2,800.00	1,580.00
GRAND TOTAL			11,422.37	4,747.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CC4/FCI20012615/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJQ 8428P

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJQ 8428P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

