

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TAN LEE MENG

BLK 508 JELAPANG ROAD

#09-106

S 670508

HUA MENG SPRAY PAINTING WORKSHOP

17, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TP 1st Cap.
Justin

Vehicle No : SJQ 8428 P
Make/Model : TOYOTA VIOS
Accident date : 10.11.2020

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bumper <i>tom</i>	1	\$ 408.60 ✓
2	Front bumper side holder @ \$133.20 <i>LH New</i>	2	\$ 266.40 <i>35</i>
3	Front bumper clips (1set) <i>new</i>	1	\$ 60.00 <i>30</i>
4	Front LH headlamp <i>at</i>	1	\$ 420.10 ✓
5	Front LH fender <i>Dented</i>	1	\$ 639.20 <i>545</i>
6	Front LH fender inner shield	1	\$ 189.70 <i>x</i>
7	Front LH fender inner shield clips (1 set) <i>new</i>	1	\$ 60.00 <i>x</i>
8	Front LH door <i>Rpr</i>	1	\$ 1399.20 <i>x</i>
9	Front LH door protector <i>at</i>	1	\$ 189.50 <i>-</i>
10	Front LH door side mirror <i>Dented</i>	1	\$ 2170.10 <i>880</i>
11	Front LH door side mirror housing	1	\$ 188.80 <i>x</i>
12	Front LH door side mirror cover <i>Rpr</i>	1	\$ 188.60 <i>x</i>
13	Front LH door black sticker (1 set) <i>new</i>	1	\$ 387.80 <i>xx</i>
14	Front LH shock absorber <i>new</i>	1	\$ 486.90 <i>✓</i>
15	Front LH knuckle arm <i>Dented</i>	1	\$ 131.40 <i>✓</i>
16	Front LH knuckle arm bearing <i>new</i>	1	\$ 871.50 <i>330</i>
17	Front LH lower arm <i>Best</i>	1	\$ 1610.10 <i>x</i>
18	Front LH drive shaft <i>new</i>	1	\$ 188.60 <i>x</i>
19	Rear LH door protector <i>new</i>	1	\$ 9856.50
			Less 25% Disc \$ 2464.13
			Total \$ 7392.38

Special Nett Items

1	Front LH sport rim <i>at</i>	1	\$ 850.00 <i>500</i>
2	Front LH tyre <i>new</i>	1	\$ 380.00 <i>x</i>
			Total \$ 1230.00

Labour Cost

1	To check wheel alignment	\$ 100.00 <i>h.v.</i>
2	Remove & reinstall front LH suspension	\$ 400.00 <i>200</i>
3	Remove, replace & repair consistent to the accident	\$ 1100.00 <i>500</i>
4	Respray painting	\$ 1200.00 <i>800</i>
		Total \$ 2800.00

Grand Total \$ 11422.38

3.8K

total 4747.37

h/s: 38K. 05 Day