

PREMIER AUTOMOTIVE SERVICES PTE LTD

Steve (LKK)

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

WM AL
16/11/77

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

16-Nov-20

3 days, L/S, By AL SH

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8032 A

1 pc	Rear bumper / DO	\$ 696.00
1 pc	Rear bumper lower cover / CUT	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X MM	\$ 58.00
1 pc	Rear bumper inner sponge 1 X MM	\$ 114.00
1 pc	Rear bumper reinforcement 1 X MM	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 X MM	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 X MM	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 X MM	\$ 36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 X MM	\$ 92.00
1 pc	Spray tyre clamp X MM	\$ 6.00
		\$ 1,959.00
		Less 10%
		\$ 195.90
		\$ 1,763.10

902
-10%
811.80

S/NETT

1 set	Rear bumper clips / APC	\$ 48.00 30
1 set	End panel inner garnish clips X MM	\$ 30.00
1 set	Bootlid stickers / APC	\$ 100.00
1 set	Reverse sensor 1 X MM	\$ 280.00
1 pc	Rear bumper protector / APC	\$ 80.00 60
		\$ 50.00 X
		\$ 50.00 X
		\$ 120.00 30
		\$ 180.00 30

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the bootlid etc

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be received and is subject to final approval from Insurance Company

To putty and spray painting on bootlid lower garnish, rear bumper, end panel, boot lid

To apply rustproofing on the repaired and replaced panels.

\$ 650.00	300
\$ 800.00	400
\$ 200.00	X
\$ 4,351.10	

Acknowledged by Repairer
Signature: