

Surveyed

Email: ishareauto@gmail.com



AUTO PTE LTD

DATE : 16.11.20

- DATE : 16.11.20**
- To resurvey before/after spray painting
 - To display damaged parts, for resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TIME OF ACCIDENT

: 19:50HRS

Jaspes

GK31346 Acknowledgment
Signature

547 Acknowledged by Repairer

Signature:

Date _____

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Disl'd</i>	1	\$ 517.70	\$ 517.70
2	FRONT BUMPER LOWER LIP <i>new</i>	1	\$ 126.30	\$ 126.30
3	FRONT BUMPER FOGLAMP COVER GRANISH RH <i>missing</i>	1	\$ 39.20	\$ 39.20
4	FRONT BUMPER LOWER GRILLE <i>Disl'd</i>	1	\$ 180.40	\$ 180.40
5	FRONT BUMPER LOWER GRILLE SIDE GARNISH <i>RH added</i>	2	\$ 18.50	\$ 37.00
6	FRONT BUMPER TOW COVER <i>new</i>	1	\$ 21.40	\$ 21.40
7	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 313.80	\$ 313.80
8	FRONT BUMPER SIDE RETAINER <i>RH changed</i>	2	\$ 15.40	\$ 30.80
9	ENGINE UNDER COVER GARNISH <i>changed</i>	1	\$ 84.30	\$ 84.30
10	ENGINE SIDE COVER GARNISH RH <i>Disl'd</i>	1	\$ 69.20	\$ 69.20
11	HEADLAMP <i>RH smashed</i>	2	\$ 795.20	\$ 1,590.40
12	HEADLAMP LOWER BRACKET <i>RH Smashed</i>	2	\$ 35.20	\$ 70.40
13	HEADLAMP WIRE HARNESS RH <i>new</i>	1	\$ 326.10	\$ 326.10
14	CENTER GRILLE <i>changed</i>	1	\$ 227.40	\$ 227.40
15	CENTER GRILLE LOGO <i>m</i>	1	\$ 28.40	\$ 28.40
16	CENTER GRILLE UPPER CHROME <i>3 new</i>	1	\$ 224.80	\$ 224.80
17	CENTER GRILLE LOWER CHROME	1	\$ 202.40	\$ 202.40
18	CENTER GRILLE BRACKET <i>2 new</i>	1	\$ 32.80	\$ 32.80
19	CENTER GRILLE INNER GARNISH <i>1 new</i>	1	\$ 22.40	\$ 22.40
20	BONNET <i>2</i>	1	\$ 550.90	\$ 550.90
21	BONNET LOCK <i>new</i>	1	\$ 87.70	\$ 87.70
22	BONNET STOPPER <i>m</i>	2	\$ 18.90	\$ 37.80
23	BONNET HINGE	2	\$ 40.50	\$ 81.00
24	BONNET INNER RUBBER <i>new</i>	2	\$ 59.20	\$ 118.40
25	FRONT SUPPORT PANEL <i>Disl'd</i>	1	\$ 555.20	\$ 555.20
26	FRONT SUPPORT LOWER APRON PANEL <i>Disl'd</i>	1	\$ 97.20	\$ 97.20

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMK5278X**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 13.11.20
 TIME OF ACCIDENT : 19:50HRS

27	FRONT SUPPORT PANEL TOP GARNISH <i>Dehd</i>	1	\$ 110.30	\$ 110.30	+
28	AIR DUCT <i>New</i>	1	\$ 59.20	\$ 59.20	+
29	WIPER TANK <i>Dehd</i>	1	\$ 75.20	\$ 75.20	+
30	WIPER TANK TUBE <i>New</i>	1	\$ 25.40	\$ 25.40	+
31	WIPER WASHER TANK MOTOR <i>New</i>	1	\$ 59.40	\$ 59.40	+
32	AIR CON CONDENSER <i>New</i>	1	\$ 810.20	\$ 810.20	+
33	AIR CON CONDENSER MOUNTING RUBBER <i>2</i>	4	\$ 39.20	\$ 156.80	+
34	AIR CON CONDENSER BRACKET <i>New</i>	2	\$ 35.40	\$ 70.80	+
35	AIR CON CONDENSER SIDE GARNISH	2	\$ 32.90	\$ 65.80	+
36	RADIATOR <i>New Cnld.</i>	1	\$ 1,250.40	\$ 1,250.40	+
37	RADIATOR RUBBER MOUNTING <i>2</i>	2	\$ 39.20	\$ 78.40	+
38	RADIATOR TOP HOSE	1	\$ 45.20	\$ 45.20	+
39	RADIATOR FAN MOTOR <i>New</i>	1	\$ 319.20	\$ 319.20	+
40	RADIATOR FAN COWLING <i>New</i>	1	\$ 125.90	\$ 125.90	+
41	RADIATOR FAN BLADE	1	\$ 78.20	\$ 78.20	+
42	RADIATOR SPARE TANK	1	\$ 50.10	\$ 50.10	+
43	HORN <i>New</i>	2	\$ 69.20	\$ 138.40	+
44	ENGINE MOUNTING (SET) <i>3 New</i>	1	\$ 799.20	\$ 799.20	+
45	ENGINE MOUNTING HOUSING RH <i>New</i>	1	\$ 174.10	\$ 174.10	+
46	AUTO GEAR BOX X Damaged ✓	1	\$ 14,876.00	\$ 14,876.00	55000 (SN)
47	FRONT FENDER RH <i>Dischd</i>	1	\$ 435.20	\$ 435.20	+
48	FRONT FENDER INNER GARNISH RH <i>Dehd</i>	1	\$ 51.50	\$ 51.50	+
49	FRONT FENDER INNER SHIELD RH <i>Dehd</i>	1	\$ 81.50	\$ 81.50	+
50	FRONT FENDER QUARTER GLASS C/W MOULDING RH <i>New</i>	1	\$ 55.20	\$ 55.20	+
51	FRONT WHEEL HOUSE RH <i>Pyris</i>	1	\$ 295.40	\$ 295.40	+
52	FRONT WHEEL HOUSE SUPPORT PANEL RH <i>Best</i>	1	\$ 129.00	\$ 129.00	+
53	FRONT WHEEL HOUSE EXTEND PANEL RH <i>Best</i>	1	\$ 139.00	\$ 139.00	+
54	FRONT CHASSIS SIDE SUPPORT PANEL (INNER) <i>New</i>	1	\$ 58.00	\$ 58.00	+
55	FRONT CHASSIS SIDE SUPPORT PANEL (OUTER) <i>New</i>	1	\$ 65.00	\$ 65.00	+
56	FRONT WINDSCREEN MOULDING <i>3 New</i>	1	\$ 169.20	\$ 169.20	+
57	FRONT WINDSCREEN SIDE MOULDING RH <i>New</i>	1	\$ 102.30	\$ 102.30	+
58	FRONT WHEEL RIM RH <i>Best</i>	1	\$ 836.20	\$ 836.20	200 (SN)
59	FRONT WHEEL CAP RH <i>Cnld</i>	1	\$ 213.60	\$ 213.60	+
60	FRONT CROSS MEMBER <i>Best</i>	1	\$ 1,250.40	\$ 1,250.40	+
61	FRONT STEERING RACK AND PINION <i>Best</i>	1	\$ 1,650.20	\$ 1,650.20	+
62	FRONT DRIVESHAFT RH <i>Best</i>	1	\$ 976.20	\$ 976.20	+
63	FRONT DRIVESHAFT OIL SEAL RH <i>New</i>	1	\$ 19.20	\$ 19.20	+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMK5278X**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 13.11.20
 TIME OF ACCIDENT : 19:50HRS

64	FRONT KNUCKLE ARM RH <i>Dend</i>	1	\$ 230.40	\$ 230.40	✓
65	FRONT LOWER ARM RH <i>Best</i>	1	\$ 160.20	\$ 160.20	✓
66	FRONT SHOCK ABSORBER RH <i>Best</i>	1	\$ 310.20	\$ 310.20	✓
67	FRONT ABS SENSOR RH <i>Mem</i>	1	\$ 299.40	\$ 299.40	+
68	FRONT WHEEL HUP RH <i>Dend</i>	1	\$ 138.30	\$ 138.30	✓
69	FRONT WHEEL HUP BEARING RH <i>m</i>	1	\$ 168.20	\$ 168.20	✓
70	FRONT STABILIZER BAR <i>Best</i>	1	\$ 189.20	\$ 189.20	✓
71	FRONT LINKAGE RH <i>Best</i>	1	\$ 49.80	\$ 49.80	✓
72	FRONT ABS PUMP <i>could</i>	1	\$ 4,992.80	\$ 4,992.80	✓ 2500(SN)
73	CENTER PILLAR INNER GARNISH <i>mem</i>	1	\$ 324.90	\$ 324.90	+
74	FRONT DOOR PILLAR (OUTER) RH <i>Mem</i>	1	\$ 899.40	\$ 899.40	+
75	FRONT DOOR SIDE MIRROR RH <i>cut</i>	1	\$ 527.40	\$ 527.40	✓
76	FRONT DOOR RH <i>Regis</i>	1	\$ 1,050.20	\$ 1,050.20	+
77	FRONT DOOR BLACK STICKER <i>part</i>	1	\$ 39.20	\$ 39.20	+
78	FRONT DOOR HINGE RH <i>Jan</i>	2	\$ 42.40	\$ 84.80	+
79	FRONT DASHBOARD <i>tom</i>	1	\$ 718.20	\$ 718.20	✓
80	FRONT SEAT RH <i>Best</i>	1	\$ 1,647.10	\$ 1,647.10	✓ 1000(SN)
81	FRONT SAFETY BELT <i>Activated</i>	2	\$ 464.20	\$ 928.40	✓
82	FRONT PASSENGER AIR BAG <i>3 Activated</i>	1	\$ 2,236.40	\$ 2,236.40	✓
83	FRONT STEERING WHEEL AIR BAG	1	\$ 1,605.20	\$ 1,605.20	✓
84	FRONT AIR BAG SENSOR <i>2</i>	2	\$ 157.20	\$ 314.40	✓
85	FRONT AIR BAG CONTROL UNIT <i>Activated</i>	1	\$ 747.20	\$ 747.20	✓
86	AIR FRONT BAG WIRE HARNESS	1	\$ 269.40	\$ 269.40	✓

1800690 S/N: 8200
 1440552

TOTAL PRICE \$ 49,499.40
 LESS 20% \$ 9,899.88
SUB TOTAL PRICE \$ 39,599.52

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Mem</i>	1	\$ 80.00	\$ 80.00	+
2	FRONT BUMPER CLIP (SET) <i>Mem</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER LOWER GRILLE CLIP (SET) <i>Mem</i>	1	\$ 60.00	\$ 60.00	20
4	FRONT BUMPER LOWER GRILLE SIDE GARNISH CLIP (SET) <i>Mem</i>	1	\$ 40.00	\$ 40.00	10
5	ENGINE UNDER COVER GARNISH CLIP (SET) <i>Mem</i>	1	\$ 80.00	\$ 80.00	30
6	ENGINE SIDE COVER GARNISH CLIP (SET) <i>Mem</i>	1	\$ 60.00	\$ 60.00	20
7	CENTER GRILLE CLIP (SET) <i>Mem</i>	1	\$ 60.00	\$ 60.00	20
8	CENTER GRILLE INNER GARNISH CLIP (SET) <i>Mem</i>	1	\$ 60.00	\$ 60.00	+
9	FRONT SUPPORT PANEL SEALANT <i>Mem</i>	1	\$ 150.00	\$ 150.00	+
10	FRONT WIPER PANEL GARNISH CLIP (SET) <i>Mem</i>	1	\$ 50.00	\$ 50.00	+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMK5278X**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 13.11.20
 TIME OF ACCIDENT : 19:50HRS

11	FRONT WINDSCREEN SEALANT <i>2x4</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
12	FRONT WINDSCREEN INNER SEAL <i>5m</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
13	FRONT FENDER INNER SHIELD CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
14	FRONT WHEEL HOUSE SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
15	CENTER PILLAR INNER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
16	FRONT DOOR PILLAR (OUTER) SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
17	FRONT PILLAR QUARTER GLASS SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
18	FRONT PILLAR QUARTER GLASS INNER SEAL RH <i>2x4</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
19	FRONT PILLAR QUARTER GLASS SOLAR FILM RH <i>5m</i>	1	\$ 250.00	\$ 250.00	<i>+</i>
20	FRONT DASHBOARD CLIP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00	<i>50</i>
21	FRONT WHEEL TYRE RH <i>Runaround</i>	1	\$ 480.00	\$ 480.00	<i>180</i>
22	COOLANT <i>new</i>	1	\$ 80.00	\$ 80.00	<i>50</i>
23	DOOR VISOR (SET) <i>new</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
24	AUTO GEAR BOX OIL <i>new</i>	1	\$ 480.00	\$ 480.00	<i>100</i>
25	BRAKE OIL <i>new</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
<i>600</i>			TOTAL	\$ 3,260.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,400.00	<i>1400</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>1280</i>
3	TUFF COAT	\$ 250.00	<i>80</i>
4	WIRING, BULB CHECKING	\$ 180.00	<i>30</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>X</i>
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>60</i>
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>60</i>
8	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>X</i>
9	REMOVE AND REFIX ENGINE MOUNTING	\$ 450.00	<i>X</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>X</i>
			<i>150</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMK5278X**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 13.11.20
 TIME OF ACCIDENT : 19:50HRS

12	FRONT CHASSIS ALIGNMENT	\$ 250.00	X
13	REMOVE AND REFIX AUTO GEAR BOX	\$ 450.00	280
14	LIFT UP AND REFIX ENGINE	\$ 680.00	280
15	REMOVE AND REFIX FRONT CROSSMEMBER	\$ 350.00	150
16	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	220
17	REMOVE AND REPLACE STEERING RACK AND PINION	\$ 350.00	120
18	FOUR WHEEL ALIGNMNET	\$ 120.00	80
19	REMOVE AND REFIX FRONT WINDSCREEN GLASS	\$ 120.00	X
20	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	X
21	REMOVE AND REFIX FRONT DASHBOARD	\$ 850.00	220
22	REMOVE AND REFIX FRONT PILLAR QUARTER GLASS	\$ 80.00	40
23	RESET RADIO SYSTEM	\$ 200.00	X
24	REMOVE AND REFIX ABS PUMP	\$ 480.00	120
25	RESET ENGINE LIGHT	\$ 350.00	X
26	RESET ABS LIGHT	\$ 350.00	X
27	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 11,600.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 42,859.52
 TOTAL LABOUR COST : \$ 11,600.00
 TOTAL REPAIR COST : \$ 54,459.52

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

Adrian S
 u/s 18/11/20

18 Days

total 28745.52

u/s 23K

23K

4540