

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012630/KGS3Q2**Date:** 07/04/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100423339
Claimant
Vehicle No : SMG1384U **Insured Vehicle No :** GBD9947P
Date of Loss: 12/11/2020 Nature of Claim: TP Claim No: 5164770777SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG1384U**
Make & Model: TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A) Engine No: 2ZR2A53111
Reg. Date: 05/12/2018 (Man. Year: 2018) Chassis No: ZVW506133141
Colour: Metallic Pearl White Odometer: 234680 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: APLUS 8 mm Rear Left Side: APLUS 8 mm
Front Right Side: APLUS 8 mm Rear Right Side: APLUS 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,775.56	1,820.04	1,955.52	51.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	755.00	1,425.00	65.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,955.56	2,575.04	3,380.52	56.76
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	5,955.56	2,050.00	3,905.56	65.58
+ GST 7.00/7.00% (S\$)	416.89	143.50	273.39	65.58
Nett Amount (S\$)	6,372.45	2,193.50	4,178.95	65.58
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,495.50		

INSPECTION

Date of Assignment: 17/11/2020

Date Inspected: 17/11/2020 Inspected At:

Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	61.75 FL	*61.75 FL
2	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	53.75 FL	*53.75 FL
3	1		*REAR TAILGATE TOYOTA LOGO	Necessary	61.10 FL	*61.10 FL
4	1		*REAR TAILGATE OUTER GARNISH	Mtg Cracked	741.35 FL	*741.35 FL
5	1		*REAR TAILGATE INNER RUBBER	Serviceable	281.50 FL	*- FL
6	1		*REAR BUMPER	Buckled	928.35 FL	*512.60 FL
7	2		*REAR BUMPER SIDE RETAINER	Serviceable	282.80 FL	*- FL
8	1		*REAR BUMPER DIFFUSER	Cracked	379.00 FL	*379.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	458.00 FL	*350.50 FL
10	1		*REAR BUMPER TOWING COVER	Serviceable	61.00 FL	*- FL
11	1		*REAR END PANEL	Repair	970.25 FL	*- FL
12	1		*REAR END PANEL INNER GARNISH	Serviceable	381.90 FL	*- FL
13	1		*SET REAR PARKING SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,940.75	2,360.05
- List Item Discount on L Items 25.00/25.00% (\$)	1,165.19	540.01
Total Parts (\$)	3,775.56	1,820.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TUFFKOTE	New	100.00	0.00
2	WIRING	New	80.00	15.00
3	SPRAY PAINTING	New	1,000.00	440.00
4	LABOUR CHARGES	New	1,000.00	300.00
Gross Labour Cost (\$\$)			2,180.00	755.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >