

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

12/11/2020

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SMG1384U

1pc	rear tailgate "PRIUS" emblem	\$	61.75
1pc	rear tailgate "HYBRID" emblem	\$	53.75
1pc	rear tailgate "TOYOTA" logo	\$	61.10
1pc	rear tailgate outer garnish	\$	741.35
1pc	rear tailgate inner rubber	\$	281.50
1pc	rear bumper	\$	928.35
2pcs	rear bumper side retainer @\$141.40	\$	282.80
1pc	rear bumper diffuser	\$	379.00
1pc	rear bumper reinforcement	\$	458.00
1pc	rear bumper towing cover	\$	61.00
1pc	rear end panel	\$	970.25
1pc	rear end panel inner garnish	\$	381.90
			<hr/>
		\$	4,660.75
	less 25%	\$	1,165.19
		\$	<hr/> 3,495.56
1set	rear parking sensor	s.nett \$	280.00
	tuffkote	\$	100.00
	wiring	\$	80.00
	spray painting	\$	1,000.00
	labour charges	\$	1,000.00
	Total	\$	<hr/> <hr/> 5,955.56

