

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

AKA
LKK
Kenneth
17/11/20

12/11/2020

Owner: HYMS CAR LEASING PTE LTD

Not Withheld
L1 Rep @
Penang After Palm
3 days

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SMG1384U

		<i>N</i>	\$ 61.75	✓
1pc	rear tailgate "PRIUS" emblem	<i>N</i>	\$ 53.75	✓
1pc	rear tailgate "HYBRID" emblem	<i>N</i>	\$ 61.10	✓
1pc	rear tailgate "TOYOTA" logo		\$ 741.35	✓
1pc	rear tailgate outer garnish	<i>Sm</i>	\$ 281.50	X
1pc	rear tailgate inner rubber	<i>Bu</i>	\$ 928.35	✓
1pc	rear bumper	<i>Sm</i>	\$ 282.80	X
2pcs	rear bumper side retainer @\$141.40	<i>CM</i>	\$ 379.00	✓
1pc	rear bumper diffuser		\$ 458.00	✓
1pc	rear bumper reinforcement	<i>Sm</i>	\$ 61.00	X
1pc	rear bumper towing cover	<i>N</i>	\$ 970.25	X
1pc	rear end panel	<i>Sm</i>	\$ 381.90	X
1pc	rear end panel inner garnish			
			\$ 4,660.75	
			\$ 1,165.19	
	less 25%		\$ 3,495.56	

1set rear parking sensor

Shan s.nett \$ 280.00 *2015*

tuffkote
wiring
spray painting
labour charges
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

		<i>N</i>	\$ 100.00	X
			\$ 80.00	<i>15/</i>
			\$ 1,000.00	<i>440</i>
			\$ 1,000.00	<i>300</i>
			\$ 5,955.56	

