

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Lim Chin Huat

TK MOTOR WORKSHOP

KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL: 9627 3323 FAX: 6844 2641

CO. REG NO: 53049097L

Date: 29/12/2020

TP Budget Direct.

Denise.

345 Choa Chu Kang Ave 3 #18-30

Singapore 689876

Accident Date: 13/11/2020

Estimate Cost of Repair Bill To Honda Car No: SLJ9580M

Model: Honda Vezel

Chassis No: RU1-1206247

1 pc Rear Bumper torn	865.80 ✓
8 pc Rear Bumper clip New	30 ✓
1 pc Rear R/H Side Bumper Repair	195 X
4 pc Rear R/H Side Bumper clip New	10 X
1 pc Rear R/H Fender Repair	931.40 X
1 pc Rear R/H Fender Arc Garnish Cut	198.20 ✓
11 pc Rear R/H Fender Arc Garnish Clip New	20 ✓
1 pc Rear R/H Door Dented	995.30 ✓
2 pc Rear R/H Door Rubber New	187.60 X
1 pc Rear R/H Door Lock New	296.50 X
1 pc Rear R/H Door Power Window Gear & Motor Dangle	358.40 ✓
1 pc R/H side skirt Cut	466.80 ✓
13 pc R/H side skirt clip New	30 ✓
1 pc Rear R/H sport Rim Cut	480(SN) 600(SN)
1 pc Rear R/H Tyre New	350(SN) X

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 9627 3323 FAX: 6844 2641
CO. REG NO: 53049097L

Estimate Cost of Repair Bill To Honda Car NO: SLJ9580M1

1 pc Rear R/H Fender Inner shield	Dehand	252.10 ✓
1 pc Rear	Axle [redacted] New	1583.60 x
1 pc Rear R/H	Shock Absorbers New	385 x
1 pc Rear R/H	Wheel [redacted] Hub & Bearing New	378.60 x
1 pc Centre R/H	Door Pillar New	845.90 x

To Check Wiring

30.
~~\$50.00~~

To Spray Painting

~~600.
\$1,200.00~~

To Remove & Refix Rear Undercarriage

x
~~\$250.00~~

To Remove & Refix Interior Upholstry & Cushion

50
~~\$150.00~~

To Measure, Drill The Replaced Rear Bumper, Position & Reinstall Reverse Sensor, Control Unit & Test For Functioning

50.
~~\$80.00~~

To Conduct Computer wheel Alightment

80
~~\$90.00~~

Labour Charge For Panel Beating, Removing All Damage Parts & Replacing of The New Parts Etc

650
~~\$900.00~~

List 321660

Labour: 1460

Len 20% 257378

total: 451328

S.N.: 480

L/S: 3.6K

06 Days