

CAR PRO AUTO
 SKS 1414C CHASSIS WDD2120362B194379

Estimate - Parts(s)

S/N	Qty	Descriptions	Amount		
LIST ITEMS:-					
1	1	rear bumper ✓ DD	1760	1698	✓
2	2	rear bumper side retainer ✓ BR	150		✓
3	1	rear bumper lower trim garnish ✓ CUT	270		✓
4	1	rear bumper lower chrome moulding ✓ CUT	295	258	✓
	2	rear bumper LH & RH exhaust chrome moulding ✓ CUT	330		✓
5	1set	rear bumper fasteners ✓ NEC	55	30	✓
6	1	rear bumper reinforcement ✗ NN	910		✗
7	1	rear bumper towing cover ✓ CUT	98	67	✓
8	1	rear bumper inner center frame ✓ BR	155		✓
9	1	rear bumper inner lower center cover ✓ BR	155		✓
10	1	rear bumper inner switch sensor module bracket ✓ NEC	105	80	✓
11	2	4-rear bumper reverse distance sensor ✓ Shorted	760	380	✓
12	1	bootlid ✓ DD	2990	2470	✓
13	1	bootlid inner lock ✓ Jammed	340	286	✓
14	1	bootlid inner trim ✗ NN	288		✗
15	1	bootlid inner trim fasteners ✗ NN	28		✗
16	1	bootlid chrome moulding ✗ NN	185		✗
17	1	bootlid logo emblem ✓ NEC	95	75	✓
18	1	E250 emblem ✓ NEC	95	77	✓
19	1	7G tronic emblem ✓ NEC	95	81	✓
20	1	2-taillamp LH & RH assy (RH) ✓ BR	1500	652	✓
21	2	taillamp LH & RH lower bracket holder ✓ BR	165		✓
	1	2 bootlid lamp LH & RH (RH) BR	980	388	✓
22	1	rear end panel ✗ Repair	1395		✗
23	1	rear end panel top garnish ✓ CRU	220		✓
24	1	rear end panel top garnish fasteners ✓ NEC	45	20	✓
25	2	rear fender LH & RH inner trim board ✗ NN	680		✗
26	1 set	rear fender LH & RH inner trim board fasteners ✗ NN	75		✗
27	1	rear exhaust muffler ✗ NN	1298		✗
28	2	rear fender LH & RH side top garnish (Bumper moulding) ✓ NEC	165		✓
			15682		
		Less 10%	1568.2		
			14113.8		
		Special Nett Item			
	1	rear end panel sealant	80		✗ NN

8172
 -10%
 7353.80

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount	
		B/F		
		LABOUR & OTHER CHARGES:-		
1		To panel beat and renewal of all necessary damaged body parts	800	650
2		To check wiring and rewire	60	30
3		to remove and reinstall / realign rear exhaust	120	30
4		to remove and reinstall reverse sensor	120	30
5		To anti-rust	100	30
6		to remove and reinstall bootlid components	100	50
7		To putty and spray-paint of affected areas	800	650
8		To clear/reset fault code	250	150
			1620	
				2350

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Steve (LKK)
18/11/20
Without Prejudice
L/S
Resurvey After Spray
4 repair days

P - 7353.80
L - 1620
= 8973.80

L/S - 7179.03
= 7200