

CHOON HOCK MOTOR TRADING CO

Not Authorised

11 Sep \$2900/-
Resurvey After Paint

5 days

17 November 2020

ESTIMATE BILL TO REPAIR GX 1928 H TOYOTA LITEACE 5 DR VAN

1 pce tailgate	939.70	RM	\$ 1,240.50	✓
1 pce tailgate inner trimboard		CM	\$ 144.90	✓
1 pce tailgate inner lock assy.		Tr	\$ 288.50	✓
1 pce tailgate inner lock actuator assy.		Tr	\$ 160.50	2
1 pce tailgate inner lock catch		n	\$ 88.10	X
2 pcs tailgate dampers		Sm	\$ 632.00	X
1 pce tailgate emblem sticker		mc	\$ 51.90	✓
1 pce tailgate "LITEACE" sticker		mc	\$ 36.20	✓
1 pce rear panel	416.70	SM	\$ 513.80	2
1 pce rear bumper fascia	381.10	Del	\$ 442.50	✓
2 pcs rear bumper reflectors		MS	\$ 114.20	4
2 pcs rear bumper side retainers		in	\$ 48.80	X
			\$ 3,761.90	
			less 25%	\$ 940.50
				\$ 2,821.40

S/NETT

1 set tailgate inner trim board clips	mc	\$ 45.00	✓
1 pce tailgate "70km/h" sticker	mc	\$ 20.00	125m
1 set reverse sensors	scr	\$ 300.00	200m
Transfer tailgate glass assy. and refit		\$ 120.00	✓
Remove tailgate fittings to new tailgate assy.		\$ 120.00	60l
Wirings		\$ 80.00	20l
Renew reverse sensors, transfer to new bumper assy.		\$ 180.00	50l
Remove spare wheel and rack assy. refit	na	\$ 100.00	X
Remove rear windscreen	Remove	\$ 200.00	X
Panel beating		\$ 1,000.00	600l
Painting		\$ 1,000.00	450l
Rustproof		\$ 200.00	60l
Total amount :		\$ 6,186.40	

6379.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Mailing address: 28 Surrey Road #18-03 Singapore 307762 Reg No: 30568200L
Tel: (65) 64530778 Email: choonhockmotor@gmail.com

CHOON HOCK MOTOR TRADING CO

17 November 2020

ESTIMATE BILL TO REPAIR GX 1928 H TOYOTA LITEACE 5 DR VAN

1 pce spare wheel rack assy.	distorted	\$220.00
1 pce spare wheel rack fasterning bracket	bent	\$ 38.00
		\$258.00
	less 25%	\$ 64.50
Additional amount :		<u>\$193.50</u>

Mailing address : 28 Surrey Road #18-03 Singapore 307762 Reg No: 30568200L
Tel: (65) 64530778 Email: choonhockmotor@gmail.com