

Section A - Accident Details

Registration Number	SHC4645C
Case Reference Number	TAX/11/20/2019
Registration Date	20/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHAN HUANG CHIN
Type of Accident	Head to Rear
Accident Date and Time	10/11/2020 8:40 AM
Accident Reported Date and Time	10/11/2020 11:43 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108753
Special Instruction to ARC, if any	TP/ REAR PORTION
Prepared Date and Time	10/11/2020 1:41 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$1,476.00	\$300.00
Total Spare Part Cost	\$3,965.35	\$1,119.58
Total Other Cost	\$680.00	\$50.00
TOTAL COST	\$6,797.35	\$1,869.58
Lump Sum Total	\$6,800.00	\$1,850.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	13/11/2020 11:41 AM	13/11/2020 11:13 AM
Signature		
Remarks	Total number of repair days = 3 days SUP = 0 day	L/S, after paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2011-0407	Invoice Number	
Quotation Date	26.11.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$100.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,476.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$680.00	\$50.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given

CR4
Nec
SUC
SUC
SUC
SUC
SUC
Nec
SUC
SUC
SUC

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	Notes
52575-47020			BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X SVC
58308-47011			UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X SVC
67005-47241			TAILGATE ASY	0.00	\$1,007.90	0.00	\$0.00	Replace	Not Given	X SVC
76801-47070-B0			TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	X SVC
75310-47020			EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X SVC
75374-47051			NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X SVC
75442-47030			NAME PLATE (PRIUS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	X SVC
75443-47030			NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X SVC
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X SVC
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X SVC
76085-47910			SPOILER REAR	1.00	\$953.70	25.00	\$715.28	Replace	Replace	X CR4
81006-47011			3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Not Given	X SVC
58307-47060			END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	X SVC
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X SVC
Total					\$6,057.01		\$1,191.31			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81006-47011	3RD BRAKE LAMP	1.00	\$231.30	10.00	\$208.17	Replace	Replace
Total					231.30		208.17		

1399.48 /

- 202

+ 1119.58 /
+ 400.00 /
+ 350.00 /

1869.58 /

4/3 \$1850 /
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal notification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____