

ASS. REC. BY:

Steve

REF:

CS/CT120012652/F3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GRX 7621E

Yr Regn:

10/11/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV350

c.c

2488

Colour:

Red

A/C:

Insured / Std / NI / N

Sp. Reading

9385

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

JNIMC9E 26200-32132

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15C

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

14/11/20

D.O.I.

9/12/20

Survey held at

EMICIP Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front LH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-7LK

finalize \$1949.91 (P/P, before GST). 3 repair days.

RED: 2122.22, 52%

Date/Time, File, Pass to?



: Prell. Report



: Final Report

1)

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

S + RS, SI

Photos

Others

TOTAL

Rep. Form:

Lump Sum / LE: /

# EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBK7621E

MAKE & MODEL : NISSAN/NV350 PANEL VAN 2.5MT 5DR

CHASSIS NO : JN1MC2E26Z0032132

DATE : 19 NOV 2020

CLAIM TYPE : TP CLAIM

D.O.A : 14 NOV 2020

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	LIST PRICE	TOTAL PRICE
1	1	FRONT BUMPER	BR	\$ 571.90	\$ 571.90
2	1	FRONT BUMPER SIDE RETAINER	BR	\$ 147.00	\$ 147.00
3	1	FRONT FOG LAMP GARNISH LH	X	\$ 104.70	\$ 104.70
4	1	HEADLAMP ASSY LH	INT	\$ 672.00	\$ 672.00
5	1	FRONT STEP PANEL GARNISH LH	X	\$ 235.00	\$ 235.00
6	1	FRONT WHEEL HUB CAP LH	X	\$ 151.20	\$ 151.20
7	1	SIDE MIRROR LH	X	\$ 553.90	\$ 553.90
				<b>\$ 2,435.70</b>	<b>\$ 2,435.70</b>

TOTAL PRICE	\$ 2,435.70
DISCOUNT: 10%	\$ 243.57
SUB TOTAL PRICE	<b>\$ 2,192.13</b>

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	FRONT BUMPER CLIPS SET	ARC	\$ 50.00	\$ 50.00
2	1	COMPANY REGISTRATION STICKER	ARC	\$ 30.00	\$ 30.00

TOTAL S/NETT	\$ 80.00	<b>\$ 80.00</b>
--------------	----------	-----------------

### Labour Charges

1	To panel beat & straighten damaged panels. To remove & replace parts.	\$ 700.00	200
2	To apply anti rust coat and Tuff Kote affected areas	\$ 50.00	30
3	To check and rectify lighting & wiring harness	\$ 50.00	30
4	To Spray painting Front Bumper & front left door & affected parts	\$ 700.00	400
5	To do artwork company sticker.	\$ 300.00	150

TOTAL LABOUR	\$ 1,800.00
--------------	-------------

### Total Cost of Repairs

<b>\$ 4,072.13</b>
--------------------

(Total parts + Total S/Nett + Total Labour Cost)

Steve (LKK) WLC AL  
9/12/20, 9.15am

3 days

P/P

Ry BOL SMJ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: