

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20012653/DTF3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

Claimant
Vehicle No : FBH1550G

Insured Vehicle No : SLL3213C

Date of Loss: 12/11/2020

Nature of Claim: TP

Claim No: 630894

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBH1550G**

Make & Model: YAMAHA AEROX GDR155A, 155cc CVT ABS

Engine No: G3J1E0402426

Reg. Date: 22/08/2019 (Man. Year: 2019)

Chassis No: MH3SG4620KJ066751

Colour: Silver

Odometer: 24495 km

Engine Capacity: 155 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80R14

Rear Tyre Size:

140/70 R14

Front Left Side: Maxxis 2 mm

Rear Left Side:

Maxxis 2 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,428.50	2,709.00	719.50	20.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	470.00	260.00	210.00	44.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	3,898.50	2,969.00	929.50	23.84
Approved Total (Overridden) (\$)		2,300.00		
Nett Amount (\$)	3,898.50	2,300.00	1,598.50	41.00

INSPECTION

Date of Assignment: 17/11/2020

Date Inspected: 17/11/2020 Inspected At:

S9 Motor Trading Pte Ltd (HQ)
4001 ANG MO KIO INDUSTRIAL
PARK 1 #01-21
Singapore 569622

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Jan 2021)	
Parts:	N/A	YAMAHA AEROX GDR155A 155cc CVT ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH1550G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FORK TUBE	Distorted	520.00 FL	*520.00 FL
2	1		*HANDLE BAR	Distorted	185.00 FL	*185.00 FL
3	1		*BRAKE LEVER	Cut	95.00 FL	*95.00 FL
4	2		*FRONT PANEL-L/RH	Cut	280.00 FL	*280.00 FL
5	1		*FRONT SIDE YAMAHA EMBLEM	Repeated	105.00 FL	*- FL
6	1		*FRONT MUDGUARD	Cut	245.00 FL	*245.00 FL
7	1		*SET BALANCER	N/s Cut	180.00 FL	*90.00 FL
8	1		*REAR TAIL SIDE PANEL N/S	Cut	165.00 FL	*165.00 FL
9	1		*YAMAHA STICKER	Necessary	95.00 FL	*95.00 FL
10	1		*LH CENTRE PANEL COVER (BLACK)	Not Necessary	195.00 FL	*- FL
11	1		*BELLY PAN	Not Necessary	255.00 FL	*- FL
12	1		*REAR SIDE PANEL RH	Cut	255.00 FL	*255.00 FL
13	1		*MAIN STAND	Cut	195.00 FL	*195.00 FL
14	1		*AIR BOX COVER	Cut	110.00 FL	*110.00 FL
15	1		*TRANSMISSION COVER	Cut	135.00 FL	*135.00 FL
16	1		*FRONT TOP COWLING	Broken	140.00 FL	*140.00 FL
17	1		*SET REAR PILLION GTR FOOT PEG	N/s Cut	189.00 FS	*150.00 FS
18	1		*SET MIRROR (FIBRO SERIES)	N/s Cut	280.00 FS	*220.00 FS
19	1		*BODY DECAL STICKER	Necessary	120.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,744.00	2,960.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	315.50	251.00
Total Parts (\$\$)	3,428.50	2,709.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	40.00	0.00
2	REMOVE & REPLACE PARTS,ALIGN & ETC	New	280.00	180.00
3	REMOVE & REPLACE FORK TUBE & TOP UP FORK OIL	New	150.00	80.00
Gross Labour Cost (\$\$)			470.00	260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >