

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

MS First Capital Insurance Ltd

36 Robinson Road
 #16-01 City House
 Singapore 068877
 Tel : 6507 - 3848
 Fax : 6507 - 3849

Quotation

DATE : 19.11.2020
 VEH NO : SLH1227Y
 MODEL : BMW 523i
 D O A : 13.11.2020
 YR REF : SHC3788E

Justin.

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLH1227Y (BMW 523i)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Repair</i>	1	1,468.00 <i>X</i>
2	Front Bumper Side Holder - RH <i>Not new</i>	1	102.00 <i>X</i>
3	Front Bumper Logo <i>New</i>	1	68.00 <i>✓</i>
4	Front Fender - RH <i>Dented</i>	1	895.00 <i>✓</i>
5	Front Fender Outer Garnish - RH <i>Int</i>	1	48.00 <i>✓</i>
6	Front Fender Inner Shield - RH <i>Deformed</i>	1	192.00 <i>✓</i>
7	Front Wheel Rim - RH <i>Int</i>	1	1,250.00 <i>850 (SN)</i>
8	Front Lower Arm - RH <i>Bent</i>	1	425.00 <i>✓</i>
9	Front Control Arm - RH <i>Bent</i>	1	285.00 <i>✓</i>
10	Front Upper Arm - RH <i>Bent</i>	1	308.00 <i>✓</i>
11	Front Knuckle Arm - RH <i>Damaged</i>	1	822.00 <i>✓</i>
12	Front Wheel Hub c/w Bearing - RH <i>Damaged</i>	1	452.00 <i>✓</i>
13	Front Shock Absorber - RH <i>Not new</i>	1	545.00 <i>X</i>
14	Front Door - RH <i>Dented</i>	1	1,774.00 <i>✓</i>
15	Front Door Lock - RH <i>Not new</i>	1	546.00 <i>X</i>
16	Front Door Weatherstripe - RH <i>New</i>	1	248.00 <i>✓</i>
17	Front Door Wing Mirror - RH <i>Not new</i>	1	873.00 <i>X</i>
18	Rocker Panel Outer Skirting - RH <i>Deformed</i>	1	688.00 <i>✓</i>
19	Rear Door - RH <i>Dented</i>	1	1,688.00 <i>✓</i>
20	Rear Door Lock - RH <i>Not new</i>	1	495.00 <i>X</i>
21	Rear Door Weatherstripe - RH <i>New</i>	1	235.00 <i>✓</i>
22	Rear Wheel Rim - RH <i>Int</i>	1	1,250.00 <i>850 (SN)</i>
23	Rear Lower Arm - RH <i>Bent</i>	1	615.00 <i>✓</i>
24	Rear Control Arm - RH <i>Bent</i>	1	285.00 <i>✓</i>
25	Rear Knuckle Arm - RH <i>Not new</i>	1	989.00 <i>X</i>
26	Rear Wheel Hub c/w Bearing - RH <i>New</i>	1	580.00 <i>✓</i>
27	Rear Shock Absorber - RH <i>Not new</i>	1	522.00 <i>X</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SLH1227Y (BMW 523i)

Less 5%

9608
912760

S/N: 1700

17,648.00

(882.40)

\$ 16765.60

S/NET ITEMS

1	Front Bumper Clips <i>HEM</i>	1 set	\$	50.00	x
2	Front Fender Inner Shield Clips - RH <i>MW</i>	1 set	\$	30.00	✓
3	Front Door Black Tape - RH <i>MW</i>	1 set	\$	80.00	✓
4	Rocker Panel Outer Skirting Clips - RH <i>MW</i>	1 set	\$	50.00	✓
5	Rear Door Black Tape - RH <i>MW</i>	1 set	\$	80.00	✓
			\$	290.00	

Total Parts

\$ 17055.60

LABOUR CHARGE

1	To knocking & pull out RH side portion & renew above parts	\$	1,400.00	900.
2	To putty & spray up paint works	\$	1,500.00	1200.
3	To check wiring	\$	100.00	30.
4	To spray tuff coat	\$	150.00	80.
5	To transfer front door fittings	\$	150.00	80.
6	To transfer rear door fittings	\$	150.00	80.
7	To dismantle front undercarriage	\$	350.00	220.
8	To dismantle rear undercarriage	\$	350.00	180.
9	To perform wheel alignment	\$	150.00	80.

Total Labour

\$ 4,300.00

Grand Total

\$ 21355.60

NOTE : -

LKK Auto Consultants hence notify the Repairer of the following:
PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

- To resurvey before and after spray painting
- To display damaged parts for confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 13917.60

H/S: 11.1K.

07 Days.