

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI20012656/Ktf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	10/12/2021	
			Code	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMM 3149M	Veh. Inspected	CB 8300K	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10007980	Excess (\$)	0.00	
	Assign From	ABIGAIL CHOO	Assign Date	17/11/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE GL	c.c	2754	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	GDH2232002860	Colour	METALLIC SILVER	
	Odometer	11374 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/80 R15	BRIDGESTONE	9 mm	
	L/H Front Tyre	195/80 R15	BRIDGESTONE	9 mm	
	R/H Rear Tyre	195/80 R15	BRIDGESTONE	9 mm	
	L/H Rear Tyre	195/80 R15	BRIDGESTONE	9 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	14/11/2020	Inspection Date	20/11/2020	
	Survey held at	THIAM HENG HUAT PTE LTD	•		
		176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: