



# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

## 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 04 working days to complete

5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : GBK639B

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>List Items</u>				
1 pc	Tailgate assy / CRU	Bent / distorted	\$ 2,534.70	\$ 2,534.70 <i>1,850</i>
		Parts Sub-Total	\$ 2,534.70	\$ 2,534.70 <i>1,850</i>
		Discount 30.00%	\$ 760.41	\$ 760.41 <i>-30%</i>
			\$ 1,774.29	\$ 1,774.29 <i>1,295</i>
<u>Nett Items</u>				
1 pc	Tailgate inner lock <i>X SVC</i>	Bent / distorted	\$ 62.10	\$ 62.10 <i>X</i>
1 pc	Tailgate windscreen <i>/ BR</i>	Broken / deformed	\$ 1,850.00	\$ 1,850.00 <i>986</i>
2 pcs	Tailgate top hinges <i>/ BT</i>	Bent / distorted	\$ 168.00	\$ 168.00 <i>/</i>
1 pc	Tailgate weatherstrip rubber <i>X SVC</i>	Warped / deformed	\$ 238.60	\$ 238.60 <i>X</i>
1 pc	Tailgate lock striker <i>X SVC</i>	damaged	\$ 43.70	\$ 43.70 <i>X</i>
2 pcs	Tailgate absorber <i>/ BT</i>	bent/distorted	\$ 579.80	\$ 579.80 <i>226</i>
		Parts Sub-Total	\$ 2,942.20	\$ 2,942.20 <i>1,380</i>
		Discount 10.00%	\$ 294.22	\$ 294.22 <i>-10%</i>
			\$ 2,647.98	\$ 2,647.98 <i>1,242</i>

Vehicle Number : GBK639B

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Nett Items</u>				
1 pc	Tailgate glass sealant <i>/ Nec</i>	necessary	\$ 80.00	\$ 80.00 <i>/</i>
1 pc	Rear number plate -emboss <i>X SVC</i>	damaged	\$ 65.00	\$ 65.00 <i>X</i>
1 pc	Rear number plate casing <i>X SVC</i>	damaged	\$ 35.00	\$ 35.00 <i>X</i>
1 pc	Tailgate 70 logo <i>/ Nec</i>	Essential	\$ 65.00	\$ 65.00 <i>20</i>
1 pc	Tailgate "nv200" emblem <i>/ Nec</i>	Essential	\$ 55.00	\$ 55.00 <i>/</i>
1 pc	Tailgate "5 pax" logo <i>/ Nec</i>	Essential	\$ 35.00	\$ 35.00 <i>15</i>
1 pc	Tailgate "nissan" emblem <i>/ Nec</i>	Essential	\$ 60.00	\$ 60.00 <i>/</i>
1 pc	Tailgate glass moulding <i>/ Nec</i>	deformed	\$ 172.80	\$ 172.80 <i>120</i>
1 pc	Tailgate glass inner seal <i>/ Nec</i>	wrapped/deformed	\$ 38.00	\$ 38.00 <i>/</i>
14 pcs	Tailgate glass clips <i>/ Nec</i>	necessary	\$ 180.60	\$ 180.60 <i>30</i>
1 pc	Rear view camera <i>/ Mis</i>	missing	\$ 650.00	\$ 650.00 <i>200</i>
		Special Nett Sub-Total	\$ 1,436.40	\$ 1,436.40 <i>618</i>
		Spare Parts Total	\$ 5,858.67	\$ 5,858.67

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
------	------------------	---------------------------	------------------------------

		Spare Parts	Total c/f	\$	5,858.67	\$	5,858.67
1	To remove/replace tailgate windscreens.	\$	180.00	\$	150.00		100
2	To transfer tailgate components to new tailgate.	\$	180.00	\$	150.00		60
3	To remove/reinstall upholstery, luggage trims & garnish to assist repairs.	\$	220.00	\$	200.00		X
4	Labour charges to repair and panel beat rear fender inner structures, chas members, bootfloor cutting/welding and replacing the above-mentioned parts.	\$	1,800.00	\$	1,600.00		300
5	To check camera wiring functions & conduct water leakage test.	\$	180.00	\$	150.00		X
6	To putty, apply primer & spray-paint the affected areas.	\$	1,600.00	\$	1,400.00		400
7	To apply rust-proofing on repaired/replaced panels.	\$	180.00	\$	150.00		40
8	To apply paint coating after repair	\$	600.00	\$	500.00		40
		Total	\$	10,798.67	\$	10,158.67	940

The repairer has agreed to undertake the repair under a part by part Sum Basis. We have further adjusted the amount to a part by part Sum Repair of :

\$ 10,158.67

Fong Kok Heng  
Fong Kok Heng  
Qualified Appraiser



1,295  
1,242  
618  
940  
4,095

PIP  
\$4,095

3 days

# ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393 - J  
Woodlands Road  
Singapore 677978  
Tel: 6760 6271 Fax: 6764 6676

---

**VINE SPRING ENTERPRISE**  
NO. 18 BOON LAY WAY  
#03-134 TRADEHUB 21  
SINGAPORE 609966

DATE: 20/08/20

DEAR SIRs

ACCIDENT DATE: 30/07/20  
FINAL REPAIR BILL TO GBK 639 B

**PART-BY-PART REPAIRS RECOMMENDED**

BY THE SURVEYOR-----\$ 10,158.67

DOLLARS: TEN THOUSAND, ONE HUNDRED AND FIFTY-EIGHT AND  
CENTS SIXTY-SEVEN ONLY