

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III20012663/T1BA3Q2

Date:

10/05/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No : SMV3258J**Insured Vehicle No :**

SHC8993X

Date of Loss: 15/11/2020

Nature of Claim:

TP

Claim No:

MCT20110225

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMV3258J**

Make & Model: VOLKSWAGEN PASSAT B8, 1.8 TFSI (A)

Engine No: CJS310804

Reg. Date: 25/09/2020 (Man. Year: 2019)

Chassis No: WVVZZZ3CZKE139725

Colour: Silver

Odometer: 1291 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,309.23	2,582.84	726.39	21.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	2,800.00	4,520.00	61.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,629.23	5,382.84	5,246.39	49.36
+ GST 7.00/7.00% (S\$)	744.05	376.80	367.25	49.36

Nett Amount (S\$)	11,373.28	5,759.64	5,613.64	49.36
+ Loss of Use (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		180.00		
Nett Liability (S\$)		6,307.09		

INSPECTION

Date of Assignment: 17/11/2020

Date Inspected: 23/11/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2021)
Parts:	143	VOLKSWAGEN PASSAT B8 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV3258J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER PRIMED REAR BUMPER	Deformed	1,544.88 FS	*1,544.88 FS
2	1		*SPOILER PRIMER	Deformed	259.44 FS	*259.44 FS
3	1		*BUMPER REINFORCEMENT	Not Necessary	541.33 FS	*- FS
4	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Necessary	58.90 FS	*58.90 FS
5	1		*GUIDE LHR BUMPER BRACKET (UPPER)	Not Necessary	21.96 FS	*- FS
6	1		*GUIDE RHR BUMPER BRACKET (UPPER)	Not Necessary	21.96 FS	*- FS
7	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	37.61 FS	*- FS
8	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	37.61 FS	*- FS
9	10		*POP-RIVET	Necessary	11.40 FS	*11.40 FS
10	1		*SET SENSOR BRACKETS	Necessary	43.74 FS	*43.74 FS
11	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS
12	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS
13	1		*DECORATIVE MOULDING BRIGH RHR BUMPER SIDE MLDG CHROM	Cut	166.56 FS	*166.56 FS
14	1		*DECORATIVE MOULDING BRIGH BUMPER CTR MLDG CHROM	Cut	216.66 FS	*216.66 FS
15	1		*REFLECTOR RHS REFLECTOR INNER	Cracked	65.92 FS	*65.92 FS
16	1		*REFLECTOR RHS REFLECTOR OUTER	Not Necessary	65.92 FS	*- FS
17	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS
					Total Parts (S\$)	3,309.23
						2,582.84

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINT	New	3,200.00	800.00
5	SPRAY PAINTING REAR LOWER SPOILER	New	840.00	400.00
Gross Labour Cost (S\$)			7,320.00	2,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >