/03/2002	CS3/AIG18009747/Avd3-1
S. REC. BY:	Ton Chee Heng SSIGNMENT (Office)  16/11/2020  Date/Time: 36/5/18 @ 15
om (Person):	Bill to:
	e No: GBF 7797H Insured: TB 11332
	Twincar Automotive Tel: 68420051
	ei Bulait Avo > # 01-17/18
	2100465527 Claim No: 3636111274SG
Sum Insured:	Excess:
Make of Veh:	D.O.A. 28 05 201
(Client's Record)	EP. / REV 24 HRS (wp) H.O.D. Endorsement:
Date/Time: 4.3	EP. / REV 24 HRS Person Contacted: Melody Vehicle IN OUT
Date/Time A	action/Instruction (X) Estimate
	GBF 7797H - NA IAIG 18 OUG 727 183 DUA: 28/5/18
	FB 11332- NA 1A1G18009 727 173 DUA: 28/5/18
1 6 18	Dismanfled
2/12/20	Submit LS \$5400 (Red 3700,41%), 5 days

# ASSIGNMENT |

From: Date:	Veh No: 68779711 Yr Regn: 20161007
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyota Hiace c.c 2982
at Workshop m/s	Colour Silves - A/C: Insured / Std / NI / NA
of	Sp.Reading 41538 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JTFHT02P2020J386.
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi : Nil / S/Rim / STD A/Rim or
i.e.	Tyre Size: F: /35R/5C
(Policy Condition)	R: 195ASC
Remark: The veh had commenced its N/S	O/S BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 06 mm L/Bal. 96 mm
Est. Repairs: 3 days Res.: Yes or No	D.O.A. D.O.I. 31/05/18
Lum Sum: % 3 Val.: Yes or No	Survey held at Twincar.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN	OUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	9
TRAIG. PRS.	
The Charles Page Pages	
1/6/18 Submit DAR Report.	
	•
RECEIVED 0 1 JUN	2018
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 5
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) 2/12/20-Typist Add	Fee: : Site Insp (\$ )s+Rssi
*	: Interview (\$ ) Photos
Report Format : TP	: Tech. Invs (\$ ) Others
Lump Sum / <del>I.B.l.</del> : (\$ 5400	Total Marie Control of the Control o
1 3400 )	:Weekend (\$



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

			ernationale Des Experts En Auto	mobile
AIC	3 ASIA PACIFIC IN	ISURANCE PTE LTD	Ref : CS3/AIG1800	9747/Az4d3
CH	SHENTON WAY # IARTIS BUILDING NGAPORE 079120		Date: 30-05-2018	
1.		Policy Particu	lars :- (THIRD PARTY CLA	AIM)
	Insured Veh.	EB 1133Z	Veh. Inspected	GBF 7797H
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	CHIN LEE YING	Assign Date	30/05/2018
2.		Vehicle I	Particulars & Condition	
	Make & Model	- 16.30	c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	(B)	Steering	
	Brakes		Modification	
	General			
3.		Co	nditions of Tyres	
		Size	Make	Balance
_	R/H Front Tyre			mm
_	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
1.		Desci	ription of Damages	
	Andrew St		neral Information	Salv Establisher
_	Accident Date	28/05/2018	Inspection Date	
	Survey held at	TWINCAR AUTOMOTIVE P 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOH SINGAPORE 417921		
a.		5115AF ORE 417921	Remarks	where the second second second
	A) THE INSPECTION	ON WAS CONDUCTED ON A	"WITHOUT PREJUDICE" BAS	ele.
	B) THE REPAIR ES	STIMATE WAS NOT PRESEN	ITED AT THE TIME OF INSPE	CTION,
	THE REPAIRER W	AS TOLD TO PREPARE THE EASE FIND DAMAGED VEHI	ESTIMATE	nernic of GSS Art

## - FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE EB1133Z AND GBF7797H ON 28/05/2018

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY Sent: 30/5/2018 4:02:54 PM

Attachments: 30052018154917.pdf 30052018112158-0001.pdf 30052018144807.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Chin Hui Xin [mailto:huixin@n51.com.sg]
Sent: Wednesday, May 30, 2018 3:51 PM

To: Chan, Yoke Shi

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan,

Syazairdina

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE EB1133Z AND

GBF7797H ON 28/05/2018

Dear Sir/Madam,

Vehicle already at our workshop, please arrange your surveyor to PRI.

Please see attached.

Thank you

Regards, Melody Chin N-51 Automotive Pte Ltd

Office: 6842 0051 Fax: 6741 0510

www.n51.com.sg

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510

Company Reg. No.: 200714616M GST Registration No.: 200714616M

Our Ref:

**GBF 7797 H** 

Your ref:

EB 1133 Z

30 May 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY EMAIL yokeshi.chan@aig.com ONLY

NO: 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120

Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT: NEW PLUMBING SERVUCES PTE LTD

VEHICLE NUMBER: GBF 7797 H

YOUR INSURED VEHICLE NUMBER : EB 1133 Z

ACCIDENT ON 28 May 2018 ALONG CTE TOWARDS AYE BEFORE PIE CHANGI EXIT

AT ABOUT 19:00 HOURS

We refer to your email/fax dated 30 May 2018 wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD


Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-17

Singapore 417921

Contact Person

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.



FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you! Appointed surveyor

(Name & Signature)

Date & Time of Inspection:

Twincar Automotive Pte Ltd

### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid,	
	ACCIDENT STATEMENT
Date Of Report	30/05/2018 15:42
Date Of Accident	28/05/2018 19:00
Exact Location Of Accident	CTE TWDS AYE B4 PIE CHANGI EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	GBF7797H
Insured/Policyholder	
Name Of Registered Owner	NEW PLUMBING SERVICES PTE LTD
Co Reg No	201200003D

Mobile Phone No.

Email Address

Alternative Phone No OFFICE-98537797

Vehicle Particulars

Manufacturer TOYOTA Model HIACE

Exact Purpose for which vehicle was being used at WORKING time of accident

Are you claiming under your own insurance policy NO

for repair to your vehicle?

THIRD PARTY

NOEMAIL

If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE, LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

2100486923-01 Policy Number

Cover Note Number

Driver

Name of Driver ANKUSAMY BALUSAMY

Passport No/FIN G8237351P Date Of Birth 15/03/1988 Occupation OUTDOOR Date Of Driving Pass 21/08/2017

Driving Experience 0 YEAR AND 9 MONTH

Gender MALE

Mobile Number (LOCAL) +65-90454760

Fax Number

Contact Number

EMail Address NOEMAIL

### Accident Sketch Plan

### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to requidiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (POPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature Date & Time:

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Sym 30/05/18
Reported Centre Personnel's Signature

Name: NRIC/FIN No.

## VAN/LORRY (Rear)

NAC   INC   Hem	(0)	VAC	T
The state of the s			ľ
The state of the s			
			ľ
The second secon			L
	DT	V	
CITY'S	NEC	1	
A SAME TO STATE OF THE PARTY OF			
1148   993068   Rear Bumper Side Retainer 1149   993045   Rear Bumper Reinforcement			
2045 993081 Rear Bumper Step Panel	-		
2046 293079 Rear Bumper Step Garnish			
2047 993186 Rear Crash Bar		H	
USS 994023 Reverse Sensor	122	-	
1159 993327 Rear End Panel	56	V	
1163 993851 Rear LH Taillamp	7.0	V	
1164 993853 Rear LH Taillamp Garnish	SCR	/	
1165 993859 Rear LH Taillamp Panel			
1166 295116 Rear RH Taillamp	-		
1167 993853 Rear RH Taillamp Garnish			
1168   993859 Rear RH Taillann Panel			
1169   993554   Rear Apron Panel			
1289   995156   Rear LH Door			-
1350   993201   Rear RH Door			
2048 991328 Rear Door Emblem			
2049 993274 Rear Door Outer Handle			
2050 993228 Rear Door Garnish			
2051 993294 Reat Door Rubber			
1291 995194 Rear LH Door Hinge			
1352   995307   Rear RH Door Hinge 1301   993201   Rear LH Door Lock			
THE COURT OF THE COURT PARTY.			
Transfer to the Contract			
Tarana and the same and the sam			
1248   994729   Third Brake Light 1181   994543   Tailgate			
40.00	07	/	
2055 993701 Rear Rubber Stopper Bracket 1182 991328 Tailgate Emblem			
1183 994643 Tailgate Outer Handle	-		
H85 994545 Tailgate Garnish			
1193 994602 Tailgate Glass	1	-	
1194 994606 Tailgate Glass Rubber			
1195 994604 Tailgate Glass Moulding	1	-	
1196   994607   Tailgate Glass Sealant		-	
2056   994597   Tailgate Extension Mirror	1	-	
197   994629 Tailgate Lock	7.0	/	
198   994651 Tailgate Rubber	5,1	-	
199 994611 Tailgate Hinge		-	
200 994594 Tailgate Damper			
201 994613 Tailgate Inner Board			
9057   993992   Rear Wiper Arm			
058   993995   Rear Wiper Blade			
089 993997 Rear Wiper Motor			
060   993484 Rear Floor Panel			
204 995065 Spare Tyre			
061 993785 Spare Tyre Bracker			
212   993,364   Rear Exhaust Pipe			
214 993361 Rear Exhaust Mountous			
214   993361   Rear Exhaust Mounting 216   995233   Rear LH Chassis Member			

NAC	T INC	Telliste No. GBF 7			
2063		Hem Rear Sidegate	0.0	NAC	00
2063	11 1100 1101 1101	Rear Sidegate Lock			
2064	993749	Rear Sidegate Huige			
2065	The second second	Sidegate Lower Panel			
2000	and the second second	Sidegate Railing	-		
2067	100,000				
2068	991965				
2069	994496		-		
2070	992857		-		
2071	992866		-		
2072	995329	Sliding Door LH	-		
2073	995328	Sliding Door RH			
2074	994295	CATCHER CONTRACTOR AND CONTRACTOR AND			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315				
2081 1224	994316	Sliding Door Stepboard Garnish			
1225	993621	Rear LH Mudflap Rear LH Wheel Rim			
1226					
1227		Rear LH Rim Cover Rear LH Tyre			
1234	993622	Rear RH Mudflap	-		
1235	993934	Rear RH Wheel Rim	-		
1236	994025	Rear RH Rim Cover	-		
1237	995065	Rear RH Tyre	-	-	
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker	NEC	/	
		Rear Camera			-
			SCR	/	
			SCR	~	
			SCR	~	
			SCR	_	
			SCR	V	
			SCR	_	
			SCR		
			SCR	V	
			SCR		

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Votified	Est Submitted	Adj Assigned	Adj Rpt		Adj Sub	mitted	Ins Auth'ed	Status	
Main .	5 Jun 2018 Edit Reg		30 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estima	ates	S\$0.00 View R			Pending for S Report Cancel Case	urvey
М	ain	Re	eference		Claim	Details		Document	s	Show All
CLAIM SUE	FOLDER DE	TAILS			The same of the sa	PARTY NAMED IN	[Created	by adjuster]		
Insured:	SOONG A	NGELO PETER,	ID: S1585123F							
Main Claimant:	NEW PLU	MBING SERVICE	S, Co. Reg. No	.: 20120000	)3D					
Vehicle Reg. No.:	GBF7797H				Date	of Loss:		18 19:00 - :59 ns and <b>8</b> Days Fro	m LTA Reg Date (	Man Yr)]
Claim Type:	<b>TP</b> / 3636111274SG				1 22 52 200	y/Cover No.:	2100465527 (Comprehensive)			
Vehicle Reg. No. (Insured):	EB1133Z				1000000	y No. imant):				
XX 1 X 1 Z 2 Z 2 Z 2 X 2 X 2 X 2 X 2 X 2 X 2 X 2					Exce	ess:				
Repairer:	- Not App	licable - (-)								
Handling Insurer:	0.000 814 201 9000 1440	Pacific Insuranc		Dokumen Tress	ens services	STATISTICS OF	a termination of the control	Commence of the Commence of th		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Ha	ndled by A	ADRIAN LI	NG] [Final R	pt due 12/06/	2018]
ASSOCIATI	ED MAIL RE	CEIVED						1	/iew All   Compo	se Case Mai
· AIG_SG (	05/06/2018):	Request To Up	load TP GIA Rep	oort				_		
ALL ASSO	CIATED TAS	KS⊡					View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type Task	Group Subj	ect Han	dler	Assign	ed By	Completed On	Created O	n Done
No results.										

## **Claim Documents**

\*GBF7797H (3636111274SG)

[EB1133Z]

TP

NEW PLUMBING SERVICES

May 28 2018 7:00PM

[SOONG ANGELO PETER]

Up	load Documents Uplo	pad Photos   Compose New Letter   Upload Video   Upload Audio	View	View in Brow	rser ▼
Pho	otos/Images		3 per j	page ▼	•
Vo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1.	01/06/18 14:49	General View	0	Load JPG	•
2	01/06/18 14:49	General View	0	Load JPG	•
3	01/06/18 14:49	General View	0	Load JPG	•
4	01/06/18 14:49	General View	0	Load JPG	•
5	01/06/18 14:49	General View	0	Load JPG	•
6	01/06/18 14:49	General View	0	Load JPG	•
7	01/06/18 14:49	General View	0	Load JPG	•
8	01/06/18 14:49	General View	0	Load JPG	•
9	01/06/18 14:49	General View	0	Load JPG	•
10	01/06/18 14:49	General View	0	Load JPG	•
11	01/06/18 14:49	General View	0	Load JPG	•
12	01/06/18 14:49	General View	0	Load JPG	•
13	01/06/18 14:49	General View	0	Load JPG	•
14	01/06/18 14:49	General View	0	Load JPG	•
15	01/06/18 14:49	General View	0	Load JPG	•
16	01/06/18 14:49	General View	0	Load JPG	•
17	01/06/18 14:49	General View	0	Load JPG	•
18	01/06/18 14:49	General View	0	Load JPG	•
19	01/06/18 14:49	General View	0	Load JPG	•
20	01/06/18 14:49	General View	0	Load JPG	•
21	01/06/18 14:49	General View	0	Load JPG	•
22	01/06/18 14:49	General View	0	Load JPG	•
23	01/06/18 14:49	General View	0	Load JPG	•
24	01/06/18 14:49	General View	0	Load JPG	•
25	01/06/18 14:49	General View	0	Load JPG	•
26	01/06/18 14:49	General View	0	Load JPG	•
27	01/06/18 14:49	General View	0	Load JPG	•
28	01/06/18 14:49	General View	0	Load JPG	•
29	01/06/18 14:49	General View	0	Load JPG	•
30	01/06/18 14:49	General View	0	Load JPG	•
31	01/06/18 14:49	General View	0	Load JPG	•
32	01/06/18 14:49	General View	0	Load JPG	•
33	01/06/18 14:50	Dismantled Parts	0	Load JPG	•
34	01/06/18 14:50	Dismantled Parts	0	Load JPG	•
35	01/06/18 14:50	Dismantled Parts	0	Load JPG	•
36	01/06/18 14:50	Dismantled Parts	0	Load JPG	•

Phot	os/Images			▼ 🗸
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbn	ail Print
37	01/06/18 14:50	Dismantled Parts	1 Load JPC	G 🕊
38	01/06/18 14:50	Dismantled Parts	1 Load JPG	G 🗹
39	01/06/18 14:50	Dismantled Parts	● Load JPC	G 🗷
40	01/06/18 14:50	Dismantled Parts	1 Load JPG	G 🗹
41	01/06/18 14:50	Dismantled Parts	1 Load JPC	G 🗹
42	01/06/18 14:50	Dismantled Parts	1 Load JPG	G 🗷
43	01/06/18 14:50	Dismantled Parts	1 Load JPC	G 🗹
44	01/06/18 14:50	Dismantled Parts	1 Load JPC	G 🗹
45	01/06/18 14:50	Dismantled Parts	1 Load JPG	arms.
46	01/06/18 14:50	Dismantled Parts	Load JP	G 🗹
47	01/06/18 14:50	Dismantled Parts	① Load JP	
48	01/06/18 14:50	Dismantled Parts	1 Load JP	170
49	01/06/18 14:50	Dismantled Parts	Load JP	100
50	01/06/18 14:50	Dismantled Parts	① Load JP	
	01/06/18 14:50	Dismantled Parts	1 Load JP	2750
51		Non-wear Wathers and we		
52	01/06/18 14:50	Dismantled Parts		
53	01/06/18 14:50	Dismantled Parts	① Load JP	
54	01/06/18 14:50	Dismantled Parts	0 Load JP	200
55	01/06/18 14:50	Dismantled Parts	1 Load JP	
56	01/06/18 14:50	Dismantled Parts	6 Load JP	300
57	01/06/18 14:50	Dismantled Parts	● Load JP	G 🗷
58	01/06/18 14:50	Dismantled Parts	1 Load JP	G 🗹
59	01/06/18 14:50	Dismantled Parts	1 Load JP	G 🗹
60	01/06/18 14:50	Dismantled Parts	① Load JP	G 🗹
61	01/06/18 14:50	Dismantled Parts	1 Load JP	G 🗹
62	01/06/18 14:50	Dismantled Parts	1 Load JP	G 🕜
63	01/06/18 14:50	Dismantled Parts	1 Load JP	G 🗹
64	01/06/18 14:50	Dismantled Parts	1 Load JP	G 🗹
65	01/06/18 14:50	Dismantled Parts	1 Load JP	G 🗹
66	01/06/18 14:50	Dismantled Parts	1 Load JP	G 🗹
67	01/06/18 14:50	Dismantled Parts	<b>⑥</b> Load JP	G 🗹
68	01/06/18 14:50	Dismantled Parts	1 Load JP	G 💌
69	01/06/18 14:50	Dismantled Parts	1 Load JP	G 🗹
70	01/06/18 14:50	Dismantled Parts	1 Load JP	G 🗹
71	01/06/18 14:50	Dismantled Parts	1 Load JP	Compa
72	01/06/18 14:50	Dismantled Parts	O Load JP	670
73	01/06/18 14:50	Dismantled Parts	1 Load JP	-
Since 1		Dismantled Parts	O Load JP	-
74	01/06/18 14:50		1 Load JP	100
75	01/06/18 14:50	Dismantled Parts	1 Load JP	-
76	01/06/18 14:50	Dismantled Parts		4004
77	01/06/18 14:50	Dismantled Parts		
78	01/06/18 14:50	Dismantled Parts	1 Load JP	G Ø
Doci	umentation		1 per page	¥ 2
No	Finalized On	AIG Asia Pacific Insurance Pte, Ltd. (SG)		ail Print
1	05/06/18 13:00	OI GIA REPORT	1 Load PD	
2	08/06/18 10:17	TP GIA	1 Load PD	)F

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG18009747/AZ4D3S2

Date:

02/07/2018

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100465527

Claimant Vehicle No:

GBF7797H

Insured Vehicle No:

EB1133Z

Date of Loss:

28/05/2018

Nature of Claim:

TP

Claim No: 3636111274SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**GBF7797H** 

Make & Model:

Engine Capacity:

Sum Insured (S\$):

TOYOTA HIACE, 3.0 D TURBO 5 DR (M)

Engine No:

1KD2655010

Reg. Date:

20/10/2016 (Man. Year: 2016)

Chassis No: Odometer:

JTFHT02P200207386 41538 km

Colour:

Silver

2982 cc

N/A

Market Value/New Car Price:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Yes

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Yes Engine Modification:

No

Front Tyre Size: Front Left Side:

195 R15C

Rear Tyre Size:

195 R15C

Front Right Side:

Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date Inspected:

Date of Assignment:

30/05/2018

TWINCAR AUTOMOTIVE PTE LTD

31/05/2018

Inspected At:

2 KAKI BUKIT AVE 2 #01-17/18 KAKI BUKIT AUTOHUB

SINGAPORE 417921

Estimated Period of Repair:

3.0 days

ADRIAN LING Adjuster:

Manager:

Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Dented	0.00 F	*-F
2	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
3	1	*REVERSE SENSOR	Short Circuit	0.00 F	*-F
4	1	*REAR END PANEL	Dented	0.00 F	*-F
5	1	*REAR LH TAILLAMP	Scratched	0.00 F	*-F
6	1	*TAILGATE	Dented	0.00 F	*- F
7	1	*TAILGATE LOCK	Dented	0.00 F	*- F
8	1	*STICKER	Necessary	0.00 F	*-F
9	1	*REAR CAMERA	Scratched	0.00 F	*-F
F=Fr	anchise part.				
			Total Parts (S\$)	0.00	0.00

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >