



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009747/Avd3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

Date : 03-12-2020



ATTN : LOH CHEE HENG

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EB 1133Z	Veh. Inspected	GBF 7797H
Policy No.	2100465527	Coverage (\$)	0.00
Claim No.	3636111274SG	Excess (\$)	0.00
Assign From	LOH CHEE HENG	Assign Date	16/11/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTFHT02P200207386	Colour	SILVER
Odometer	41538	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/05/2018	Inspection Date	31/05/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------